

*Aviation Rulemaking
Advisory Committee*



*Service History/Fuel Tank
Safety Level Assessment*

Task Group 1

Task Group 1

Service History and Safety Assessment

at 1 July 1998

Summary

Task Group 1 was initially charged with providing “An analysis of the threat of fuel tank explosion due to internal and external tank ignition sources for the major fuel system designs making up the transport fleet, including transport airplanes with heat sources adjacent to or within the fuel tanks.”

This was interpreted as a requirement to carry out a detailed analysis of previous tank explosion events, and to carry out a flammability review of the current range of fuel system designs and tank configurations. A further task was then added to prepare a safety analysis to evaluate the safety impacts of any proposed (design) changes recommended by the other groups. Task Group 1 successfully discharged each of these responsibilities, although the detailed flammability review was transferred to (and discharged by) Task Group 5.

Review of Service History

A review of the records of the last 40 years of transport airplane operations worldwide revealed a total of 16 tank explosions relevant to this study. Analysis of these events showed that the fuel tank location was a major factor. In comparing explosion events in integral wing tanks with those located in or adjacent to the fuselage (known as “center tanks”), it was found that the rate of center tank events was considerably higher than one would expect. It was also found that whereas corrective actions to prevent recurrence of the wing tank events were in place, the exact ignition sources in the two most recent center tank events have not been identified, and do not yet have proven remedies.

It was concluded that flammability reduction measures which would reduce the rate of center tank explosions down to the level attained by wing tanks should be investigated.

Safety Assessment

Top-level functional hazard analyses (FHA's) were performed for each option to identify the significant failure conditions these options might bring to the airplane. It was noted that whereas some of the options exhibited relatively benign failure conditions, others had the potential to cause Hazardous or Catastrophic events. However, it was concluded that proper design techniques were available to reduce the frequency of these latter failure conditions to levels consistent with the requirements of FAR/JAR 25.1309. The only exception to this statement was the Explosion Suppression option, where it was not clear that the technology was sufficiently mature to permit identification of all its potential failure modes with confidence.

Contents

| | |
|---|----|
| Summary | 2 |
| 1. Introduction | 4 |
| 2. Working Practices | 5 |
| 3. Review of Service History | 5 |
| 3.1 Details of previous tank explosions | 5 |
| 3.2 Analysis of previous tank explosion events | 5 |
| Table 1 - Summary of Operational Events | 6 |
| Table 2 - Summary of Refuelling and Ground Maintenance Events | 7 |
| Table 3 - Aircraft Damage and Fatalities | 9 |
| 3.3 Service History Conclusions | 10 |
| 4. Fuel Tank Configurations | 10 |
| 5. Safety Assessment | 11 |
| 5.1 Objectives | 11 |
| 5.2 Analysis Methods | 11 |
| 5.3 Analyses | 11 |
| 5.3.1 Gaseous inerting | 12 |
| 5.3.2 Foam | 13 |
| 5.3.3 Ullage sweeping | 14 |
| 5.3.4 High flash-point fuel | 15 |
| 5.3.5 Heat reduction | 16 |
| 5.4 Safety Assessments Conclusions | 16 |
| Appendix A - Details of previous tank explosions | 17 |

1. Introduction

This report describes the work carried out by Task Group 1 to accomplish the tasks outlined below.

The objectives for Task Group 1 were derived from the Terms of Reference for the Fuel Tank Harmonization Working Group (FTHWG), as published in the Federal Register on 23rd January, 1998. Those Terms of Reference included a task to provide:

“An analysis of the threat of fuel tank explosion due to internal and external tank ignition sources for the major fuel system designs making up the transport fleet, including transport airplanes with heat sources adjacent to or within the fuel tanks.”

This task was assigned to Group 1, and was further developed at the first Working Group meeting in Washington D.C. into the following three sub-tasks:

- (1) Carry out a **detailed analysis of previous tank explosion events**, in order to determine whether any further information could be gained regarding the contributory effects of fuel type, tank location, system design philosophy, environment etc. on the incidence of tank explosions.

The objective was to better identify those circumstances in which there is an increased likelihood of explosion, such that these could be minimized in the future, and also to identify configurations/circumstances where the risk had been shown to be low such that these could be used to guide design practice in the future.

- (2) Carry out a **flammability review of the current range of fuel system designs and tank configurations** by first creating a matrix of major types of fuel tank configurations, and then to assess the flammability levels currently existing within a representative selection of those fuel tanks.

However, it became clear during early discussions that members of Task Group 5 (Fuel Vapor Reduction) already possessed the analytical tools to complete this task. It was therefore agreed that Group 1 should compile the **tank configurations matrix** and pass it to task Group 5, which would then carry out flammability analyses.

The objective of this work was to define those configurations most at risk if an ignition source were present, such that these areas received particular attention when considering future rule changes or aircraft modifications.

- (3) Prepare a **safety analysis to evaluate the safety impacts of any proposed (design) changes** recommended by the other groups.

The aim was to provide a consistent means of assessing the safety effects of each of the options, and to indicate the level of complexity such systems might require in order to meet any new rules regarding flammability and meet existing rules governing system failure conditions (e.g. JAR/FAR 25.1309).

2. Working Practices

Group 1 comprised four members. Two came from a propulsion design and certification background with aircraft manufacturers. The third member was an airline fleet engineering manager who participated in the TWA800 accident investigation, and the final member came from the propulsion certification office of the FAA.

The group discharged its various tasks through the individual efforts of its members, and held regular reviews of its progress through data exchange, through dedicated task group meetings, and through presentations and reviews of its work in front of the full Working Group on a monthly basis. In addition, because of the relationship and interdependence of the tasks of Groups 1, 5 and 8, these teams also held periodic joint meetings to exchange findings and ideas.

3. Review of Service History

The service history of the transport airplane fleet (including turbofan and turboprop airplanes) over the last 40 years was examined, and information regarding known instances of fuel tank explosion (other than those caused by post-impact crash events) was assembled. The starting point was the table of events contained in the FAA Notice on Fuel Tank Ignition Prevention Measures published in the Federal Register on April 3, 1997. The data sources used were accident and incident reports provided by investigating organizations, regulatory authorities, and original equipment manufacturers' safety-related databases. The level of details reported in the early events was sometimes limited dependent on the event location in the world and the type of event (whether it involved an internal or external ignition source).

3.1 Details of previous tank explosions

Appendix A contains a detailed description of each event and the findings of the investigating authority, followed by a description of the mitigating actions taken subsequent to the event to prevent its recurrence.

3.2 Analysis of previous tank explosion events

The 16 tank explosion events are summarized on Tables 1 and 2. They have been separated into Operational Events (i.e. those occurring on an airplane where passenger-carrying flight was intended), and Refuelling & Ground Maintenance Events. They are grouped by cause (Lightning, Engine Separation, Refuelling, Maintenance, etc.), and are then categorized by operational phase, ignition source, type of fuel tank involved, and fuel type. The mitigating actions taken subsequent to each event are summarized, and any recurring events are identified.

Table 3 gives details of the aircraft damage and lives lost due to tank explosions.

Table 1 - Summary of Operational Events

| | | 1963 | 1976 | 1965 | 1970 | 1990 | 1992 | 1989 | 1990 | 1996 |
|---|--|--|---|---|-----------------------------------|---------------------------------|---|---------------------------|------------------------------|--|
| | | Lightning Elkton 707 | Lightning Madrid 747 | UCEF/Eng sep San Francisco 707 | Eng Sep Toronto DC-8 | Eng Sep New Delhi 747-200 | Eng Sep Marseilles 707 | Sabotage Bogota 727 | Unknown Manila 737-300 | Unknown New York 747 |
| Operational Phase | Inflight | • | • | • | • | • | • | • | | • |
| | On Ground Operations | | | | | | | | • | |
| | Ground Maintenance | | | | | | | | | |
| | Refuelling | | | | | | | | | |
| Ignition Source | Lightning | • | • | | | | | | | |
| | Overwing Fire - Inflight | | | • | • | • | • | | | |
| | Static Discharge | | | | | | | | | |
| | Sabotage | | | | | | | • | | |
| | Unknown | | | | | | | | • | • |
| Tank Type | Main (Wing) = W Center = C | W | W | W | W | W | W | C | C | C |
| Fuel Type | | JP-4 / Jet A | JP-4 / Jet A | Jet A | JP 4 | Jet A | Jet A | Jet A | Jet A | Jet A |
| Mitigating action taken to minimize or prevent recurrence of root cause | Airplane Design Change | • Flow-thru' vent; surge tank suppression | • Improved bonding inside tank | • Redundant control of spar shutoff valve | • Spoiler Lockout Mechanism | | | | | • Flame Arrestors on Pump Inlets |
| | Hardware Inspection Requirements | | | | | | • Mid-spar attach't repeat inspection | | • 12 Service Bulletins | • 12 Service Bulletins |
| | Ground Support Equipment Change | | | | | | | | | |
| | Maintenance Program / Procedures Revised | | | | | • | | | • | • |
| | Operations Bulletin | | | | | | | | • | |
| | Improved Airport Security | | | | | | | • | | • |
| | None | | | | | | | | | |
| | Unknown | | | | | | | | | |
| Recurring Event | | | • Different cause | | | | | | | • |

Table 2 - Summary of Refuelling and Ground Maintenance Events

| | | 1970 Refuelling Minneapolis 727 | 1970 Refuelling Minneapolis 727 | 1973 Refuelling Toronto DC-8 | 1989 Refuelling Washington Beechjet 400 | 1967 Ground Maint. Taiwan 727 | 1974 Ground Maint. Travis AFB DC-8 | 1982 Parked Montreal DC-9 |
|---|---|--|--|---------------------------------------|--|--|---|------------------------------------|
| Operational Phase | Inflight | | | | | | | |
| | On Ground Operations | | | | | | | |
| | Ground Maintenance | | | | | • | • | • |
| | Refuelling | • | • | • | • | | | |
| Ignition Source | Lightning | | | | | | | |
| | Overwing Fire - Inflight | | | | | | | |
| | Static Discharge | • | • | | • | • | | |
| | Sabotage | | | | | | | |
| | Unknown | | | • | | | • | • Suspect dry running boost pump |
| Tank Type | Wing = W Rear Aux = RA Center = C Fwd Aux = FA | C | C | W | RA | C | W | FA |
| Fuel Type | | Jet A | Jet A | JP-4 / Jet A | Jet A / JP-4 | Jet A | JP-4 | Jet A |
| Mitigating action taken to minimize or prevent recurrence of root cause | Airplane Design Change | | | | • Installed conductive foam | | | |
| | Hardware Inspection Requirements | | | | | | | |
| | Ground Support Equipment Change | | • "Anti-static" filters introduced | | | | | |
| | Maintenance Program / Procedures Revised | | | • (probable outcome) | | • | • | • (probable outcome) |
| | Operations Bulletin | | | | | | | |
| | Improved Airport Security | | | | | | | |
| | None | • | | | | | | |
| | Unknown | | | | | | | |
| Recurring Event | | | • | | | | | |

From Tables 1 and 2, certain patterns and trends emerge:

- There are 8 wing tank events, and 8 involving center or fuselage tanks
- In the wing tank events, 5 out of 8 involved the use of wide-cut fuel (JP-4/Jet B)
- In the wing tank events, 5 out of 8 occurred in flight
- All the wing tank events involved external ignition sources - there are no known wing tank explosions due to internal ignition sources in 520 million hours of flight operations
- There were only 2 explosions due to lightning strike, with 396 million flight hours accumulated since the last event in 1976
- All the center tank events involved the use of Jet A/Jet A-1 fuel
- In the center tank events, 6 out of 8 occurred on the ground
- There are 9 operational events, and 7 refuelling and ground maintenance events

From the data, there appears to be a difference in the respective safety levels of wing tanks and center tanks.

All the wing tank events have been due to known, external ignition sources (lightning strikes, over-wing fire, refuelling, maintenance error) - there are no known internal ignition sources in 520 million hours of commercial transport fleet operation that resulted in a tank explosion. Corrective actions to prevent recurrence of these wing tank events have been in place for many years, and have been demonstrated to be effective.

By contrast however, in the two most recent center tank events the exact ignition sources have not been identified. Whilst corrective actions to identify and eliminate potential ignition sources are now being put in place, the investigation of flammability reduction is warranted since the efficacy of these actions has yet to be proven.

Over the years, center tanks have accumulated considerably fewer operating hours than wing tanks (for example, a B-737 has two wing tanks and one center tank, and therefore accumulates wing tank hours at twice the rate of center tank hours). Since the equipment in wing and center tanks is very similar, i.e. there are similar types and numbers of potential ignition sources, one would expect there to be significantly fewer center tank events than wing tank events. Actually the numbers of events are equal. This indicates that center tanks are significantly more susceptible to explosion than wing tanks.

It might be argued that the reason for this disparity is that components in the wing tanks are more often submerged than those in the center tanks, which often operate almost empty. However, this may be an over-simplification. There are several pieces of equipment inside wing tanks which routinely operate in the vapor space, such as fuel quantity probes and wiring, and partially submerged boost pumps. There is still considerable potential for the existence of ignition sources within the ullage of wing tanks. This being the case, if center tanks are experiencing considerably more explosions than might be expected relative to wing tanks, it must be that center tanks are significantly more flammable than wing tanks. Reducing the flammability in center tanks down to wing tank levels would be a worthwhile goal.

In the last 20 years (when Jet A has been the predominant fuel), there have been five tank explosion events involving center/fuselage tanks, and two wing tank events (which were both exceptional ones - see Appendix A, Event nos. 3 & 4). The continuing

incidence of center tank explosions (all of which involved Jet A fuel) indicates that these tanks have not yet reached the safety level attained by wing tanks, and that action to further reduce the flammability levels in center tanks should be considered.

Table 3 summarizes the numbers of fatalities and degree of aircraft damage resulting from all the events. As discussed earlier, the Manila B-737 and New York B-747 events are the only ones for which the corrective actions have not been proven in subsequent airline service. In any cost/benefit analyses performed elsewhere in this study, it is recommended that only those lives lost in these last two events should be counted, since formal or informal cost/benefit analyses have already been performed on the earlier events when the decisions were taken regarding the follow-on actions from those events. A total of 238 lives were lost in the two most recent events.

Table 3 - Aircraft Damage and Fatalities

| Operational Events | No. of Events | No. of Fatalities |
|-------------------------------|----------------------|--------------------------|
| Hull loss with fatalities | 6 | 539 |
| Hull loss | 2 | |
| Substantial damage | 1 | |
| | | |
| Non-Operational Events | | |
| Hull loss with fatalities | 1 | 1 |
| Hull loss | 2 | |
| Substantial damage | 4 | 1 |
| Totals | 16 | 541 |

3.3 Service History Conclusions

This study identified and analyzed 16 known instances of fuel tank explosions (other than those following impact with the ground) over the last 40 years of transport aircraft operations worldwide. The following conclusions have been drawn:

- There is a close relationship between the incidence of explosions in wing tanks and the use of wide-cut fuel.
- Wing tanks operating with Jet A type fuel have demonstrated an acceptable safety record.
- In comparison, center tanks and fuselage-mounted tanks are more vulnerable to explosion in the presence of ignition sources.
- Apart from the two most recent events (1990/Manila & 1996/New York), the causes of all the other events have been addressed by actions designed to prevent or minimize their recurrence.

It is recommended that action to further reduce the flammability levels in center tanks should be considered.

4. Fuel Tank Configurations

An extensive survey of fuel system and fuel tank configurations was conducted for the commercial transport aircraft fleet. A tabular summary was compiled for 68 different aircraft types or models, including large, medium and small turbofan aircraft, regional jets, business jets and turboprop aircraft. This described the aircraft in terms of size and range, and characterized the wing and tank configurations, the fuel capacity and presence of adjacent heat sources for each aircraft fuel system.

On completion, it was passed to Task Group 5 to facilitate selection of suitable candidate aircraft types on which to perform flammability analyses.

5. Safety Assessment

5.1 Objectives

As stated earlier, the third task assigned to Group 1 was to assess the overall aircraft-level safety implications of carrying out the modifications being investigated by the other Task Groups. Clearly, since some of these modifications involve technologies which are currently not fully mature or proven in a commercial airline environment, rigorous and detailed safety analyses down to component level could not be carried out with confidence. However, the safety assessments described below do allow some useful comparisons to be made regarding the safety impacts of the various options relative to each other. They also provide an indication of the complexity or levels of redundancy which such systems may require in order to meet the certification requirements of FAR 25.901(c) and JAR/FAR 25.1309.

5.2 Analysis Methods

A top-level functional hazard analysis (FHA) was performed for each option. This typically looks at the effects of the system not operating when required, and operating when not required, and identifies the severity of these failure conditions (using the guidance contained in Advisory Circular AC 25.1309-1A).

For each system being analyzed, Group 1 made extensive use of the more detailed knowledge of the individual task group “responsible” for that system.

The following options were the subject of safety assessments:

- Filling the ullage space with inert gas
- Filling the tank with foam
- Purging fuel vapor from the tank
- Raising the flash point of the fuel
- Reducing the heat input into the fuel

Due to the lack of commercial aircraft operational experience with explosion suppression systems, the technology was not considered sufficiently mature or well-understood to merit carrying out an analysis of its safety implications.

5.3 Analyses

For each of the “explosion protection” systems analyzed below, the condition where they failed to operate when required was classified as Minor since loss of the protection system on its own does not significantly reduce airplane safety. Clearly, loss of protection coupled with an ignition source in a flammable atmosphere would be considered a Catastrophic event. This combination of failures is the case which would actually set the required reliability (availability) of the protection system.

5.3.1 Gaseous inerting

The gaseous inerting system is assumed to be one which actively replaces the oxygen component of the air inside the tank(s) such that the resulting fuel vapor/gas mixture is too rich to be flammable. Further, it is assumed that this requires the tank to be closed from the atmosphere to prevent dilution of the inerting agent and re-oxygenation of the ullage.

The gaseous inerting system has the following functions:

- (1) To keep the oxygen concentration inside the tank below the level which will support combustion
- (2) To keep the tank differential pressure within limits
- (3) To prevent leakage of inert gas into the passenger cabin or flight deck

The functional failures are documented below.

Function: (1) To keep the oxygen concentration inside the tank below the level which will support combustion

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|---|---|----------------|-----------------------------|--|
| Fails to prevent ullage volume becoming flammable | (A) Explosion possible if ignition source present (B) None unless ignition source present (C) None unless ignition source present | Minor | N/A | Loss of protection returns tank to pre-mod condition, i.e. only vulnerable to explosion if flammable atmosphere <u>and</u> ignition source present |
| Operates inadvertently during tank maintenance | (A) Oxygen concentration inside tank depleted (B) None (C) Asphyxiation of maintenance personnel | Hazardous | 1×10^{-7} per hour | May require system inhibition interlocks as well as explicit maintenance procedures |

Function: (2) To keep the tank differential pressure within limits

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|--|--|----------------|-----------------------------|--|
| Allows tank differential to exceed maximum positive limits | (A) Wing over-pressure deformation (B) Loss of structural integrity (C) Multiple loss of life | Catastrophic | 1×10^{-9} per hour | Need dual-redundant vent valves, and an over/under-pressure relief valve |
| Allows tank differential to exceed maximum negative limits | (A) Wing under-pressure deformation (B) Loss of structural integrity (C) Multiple loss of life | Catastrophic | 1×10^{-9} per hour | Need dual-redundant vent valves, and an over/under-pressure relief valve |

Function: (3) To prevent leakage of inert gas into the passenger cabin or flight deck

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|--------------------------------|---|----------------|-----------------------------|---|
| Transfers inert gas into cabin | (A) Possible loss of tank inerting (B) None (unless pilots incapacitated) (C) Incapacitation/death of some occupants before oxygen masks deployed | Hazardous | 1×10^{-7} per hour | Consider N ₂ detector in cabin |

5.3.2 Foam

The foam “system” is assumed to comprise multiple small blocks of highly porous material which completely fill the tank interior, with negligible voids. It prevents gross over-pressure or explosion within a tank by limiting the extent of any vapor/air ignition to a small local detonation, preventing it propagating throughout the tank.

The foam “system” has the following functions:

- (1) To prevent ignition of the fuel vapor/air mixture from causing a tank explosion
- (2) To allow free movement of fuel within the tank and into the fuel delivery system to the engine(s)

The functional failures are documented below.

Function: (1) To prevent ignition of the fuel vapor/air mixture from causing a tank explosion

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|---|---|----------------|-------------------------|--|
| Fails to protect against ignition propagating into tank explosion | (A) Explosion possible if ignition source present in flammable atmosphere (B) None unless ignition source present (C) None unless ignition source present | Minor | N/A | Loss of protection returns tank to pre-mod condition, i.e. only vulnerable to explosion if ignition source <u>and</u> flammable atmosphere present |

Function: (2) To allow free movement of fuel within the tank and into the fuel delivery system to the engine(s)

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|--|--|----------------|-----------------------------|---|
| Interruption of fuel flow to the engine(s) | (A) Blockage of fuel supply to engine(s) (B) Possible multiple engine power loss requiring forced landing (C) Serious injury/death of some occupants | Hazardous | 1×10^{-7} per hour | Life limits for foam. Increased/redesigned filtration and increased frequency of filter inspections |
| Inability to transfer fuel out of a tank | (A) Fuel trapped within a tank (B) Loss of range requiring diversion (C) None | Major | 1×10^{-5} per hour | |

5.3.3 Ullage sweeping

An ullage sweeping system is one which the fuel vapor is purged from the tank ullage using forced ventilation, making the ullage too lean to be flammable.

The ullage sweeping system has the following functions:

- (1) To keep the fuel vapor concentration inside the tank below the level which will support combustion

The functional failures are documented below.

Function: (1) To keep the fuel vapor concentration inside the tank below the level which will support combustion

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|---|---|----------------|-------------------------|--|
| Fails to prevent ullage volume becoming flammable | (A) Explosion possible if ignition source present (B) None unless ignition source present (C) None unless ignition source present | Minor | N/A | Loss of protection returns tank to pre-mod condition, i.e. only vulnerable to explosion if flammable atmosphere <u>and</u> ignition source present |

5.3.4 High flash-point fuel

This option uses fuel whose flash point has been raised from the current minimum value of 100°F to a significantly higher value (say 120°F). It prevents a fuel tank explosion by maintaining the flash point above the highest temperature attainable inside a fuel tank.

High flash fuel has the following functions:

- (1) To prevent formation of a flammable vapor/air mixture within the operating temperature envelope of a fuel tank interior
- (2) To provide a fuel suitable for aircraft gas turbine engine operation

The functional failures are documented below.

Function: (1) To prevent formation of a flammable vapor/air mixture within the operating temperature envelope of a fuel tank interior

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|---|---|----------------|-------------------------|--|
| Allows formation of a flammable vapor/air mixture inside the tank | (A) Explosion possible if ignition source present (B) None unless ignition source present (C) None unless ignition source present | Minor | N/A | Loss of protection returns tank to pre-mod condition, i.e. only vulnerable to explosion if flammable atmosphere <u>and</u> ignition source present |

Function: (2) To provide a fuel suitable for aircraft gas turbine engine operation

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|--------------------------------|--|----------------|-----------------------------|---|
| Fuel causes engine malfunction | (A) Flameout (B) Possible multiple engine power loss requiring forced landing (C) Serious injury/death of some occupants | Hazardous | 1×10^{-7} per hour | Rigorous engine/airframe compatibility testing required, possibly with controlled service introduction & fleet leader program |

5.3.5 Heat reduction

This option is intended to minimize the heat added to the fuel once it is onboard the aircraft by insulating, ventilating or otherwise physically separating heat sources from fuel tanks. The intent is to prevent raising the fuel vapor above its flash point.

The heat reduction option has the following functions:

- (1) To prevent the fuel vapor inside a tank being raised above its flash point

The functional failures are documented below.

Function: (1) To prevent the fuel vapor inside a tank being raised above its flash point

| Functional Failure | Failure Condition Effect on (A) System, (B) Aircraft, (C) Occupants | Classification | Probability Requirement | Safety Design Implications |
|---|---|----------------|----------------------------|--|
| Allows fuel temperature to rise above its flash point | (A) Explosion possible if ignition source present (B) None unless ignition source present (C) None unless ignition source present | Minor | N/A | Loss of protection returns tank to pre-mod condition, i.e. only vulnerable to explosion if flammable atmosphere <u>and</u> ignition source present |

5.4 Safety Assessments Conclusions

The top-level safety analyses above indicate that some of the options under consideration could exhibit undesirable failure conditions. However, it is considered that all of these systems could be designed with sufficient integrity to meet the requirements of FAR 25.1309 such that the overall safety of a given fleet of airplanes was not compromised. For some of the options, meeting those requirements would require greater system complexity and (possibly) more onerous inspection and maintenance requirements than the options with benign failure conditions. A comparison of the relative merits of these options is therefore primarily an economic consideration, since all of the options could be made equally safe.

Appendix A - Details of previous tank explosions

Appendix A contains a detailed description of each event and the findings of the investigating authority, each followed by a description of the mitigating actions taken subsequent to the event to prevent its recurrence. The 16 events have been grouped initially into broad categories which characterize their circumstances, i.e. engine separation events, lightning strike events, ground maintenance events, refuelling events, "others" and those where the cause remains unknown.

Engine Separation Events

- | | | |
|----|--------------------------------|-------------------------------------|
| 1. | Date: 28 June 1965 | Flight phase: Takeoff climb |
| | Aircraft: Boeing 707 | Tank type: Main reserve tank |
| | Location: San Francisco | Fuel type: Jet A |

Summary of Event

Approximately 39 seconds after takeoff No.4 engine experienced an uncontained engine failure resulting in separation of the engine from the wing. The loss of the engine resulted in mechanical damage to the wing and a severe fire. The fire triggered a low order explosion in the No.4 reserve tank which resulted in the loss of the lower wing skin, lower stringers, and spar chord flanges. The loss of these components resulted in the loss of wing integrity which allowed the outer wing panel to fail and separate from the wing. The ensuing fire was extinguished by the closing of the main fuel shutoff valve either by the first officer or the flight engineer.

There was evidence of fire on the separated wing section, on the remaining wing around the point of separation, and on the No.4 engine. Fire was observed by ground witnesses, passengers and crew members, and photographed, in color, from the ground and by a passenger. The flight crew was alerted to the fire when an intermittent fire warning was observed while they were going through the engine shutdown procedure following the failure of the No.4 engine. The first officer then actuated the fire selector lever for the No.4 engine and discharged both fire extinguisher bottles to the engine. The fire was observed streaming from the right wing. Fuel was still streaming from the No.4 tank area after landing until the fire department plugged the hole in the bottom of the tank. The area around the fuel spill and the wing stub were foamed as a preventative measure while the passengers were disembarking from the aircraft.

Analysis

A disk failure resulted in an explosive failure of the No.4 engine and its separation from the wing due to high vibration and out of balance oscillation of the rotating parts of the engine. The right outer wing received so much damage to the lower load-bearing skin and associated structure that capability of the wing to sustain in-flight loads were reduced below the loads imposed, and the outer wing panel separated from the wing. Fuel from the engine fuel line was then being pumped directly into the airstream. This fuel was ignited by an undetermined source shortly after the engine separated and resulted in an explosive separation of a portion of the lower wing skin. It is believed that dangling wires from the engine separation sequence ignited the fuel. The fire was sustained by the continued supply of fuel through the engine fuel line until the flight engineer or the first officer shutoff the main fuel supply either by activating the fuel shutoff valve to the closed position or actuating the fire selector handle.

The disintegration of the third stage turbine disk cut the engine in two pieces and threw turbine debris into the wing inboard of the engine pylon. The two engine sections, each supported by only one mount on the strut, began to oscillate and separated from the wing in approximately four seconds. The strut failures were caused by the oscillation, possibly coupled with mechanical damage from flying engine parts. The engine fuel line pulled from the strut closure rib when the engine separated from the wing. Fuel was pumped through this line for an estimated 99 seconds at a rate of approximately 30,000 pounds per hour, until the fuel valve was shut off by the action of either the first officer or the flight engineer. A second fuel source was the fuel line on the forward face of the main spar which had a loosened fitting that leaked and supplied fuel for a fire over the strut center spar between the front spar and the nacelle closure rib. A third possible flammable fluid source was the ruptured slat hydraulic line on the inboard gap cover area.

The source of the ignition cannot be determined, but the possible sources included the engine exhaust, hot turbine parts, or arcing from exposed electrical leads. The latter is the most probable source because there was an appreciable time lapse between observation of the fuel spray and ignition. The fuel sources wetted much of the upper wing surface before ignition occurred.

The fact that No.4 main tank was full of fuel probably prevented more extensive fire damage to that area of the upper wing surface because the fuel acted as a heat sink. The fire in this area reached temps ranging from approximately 870 - 1165°F, based on damage caused to the metal.

The damage to the right outboard wing section top and bottom skin and ribs could only have been caused by an over-pressure in the reserve tank. This is demonstrated particularly by the manner in which the lower skin separated from the aircraft. The entire panel was forced straight down, taking the attaching flanges of both spars with it. This is plainly the result of a low order explosion. The source of ignition for this explosion could not be determined but could have been auto-ignition, burn through, or hot surface ignition from a localized hot spot.

The final separation of the wing followed the explosion in the reserve tank. The wing separation is not believed to have been simultaneous with the explosion. The indications of yaw and vertical oscillation on the flight recorder readout and the location of the wreckage on the ground indicate that the wing section remained on the aircraft approximately 10-11 seconds after the separation of the lower skin panel.

The heat damage to the wing structure was not considered to have been a major factor in the wing failure. Rather, the loss of lower skin panel, stringer, mid spar chord flanges reduced the load carrying capability of the wing below that required to support a 1 "g" condition, thus leading to the failure.

Laboratory tests of the fuel samples taken from the six remaining fuel tanks on the aircraft revealed no significant deviation from the specification established for Jet A turbine engine fuel. It was estimated that the fuel temperature in the tanks at the time of the accident was between 70-80°F. The flammability limit of Jet A fuel was reported by the FAA to be from 90-170°F. Ambient temperature prior to the flight were recorded as 77°F.

Mitigating Actions Taken:

Airplane design change were made to incorporate redundant wiring paths to close spar and engine high pressure valves when the fuel shutoff or fire handle switch is activated. Engine assembly procedures were modified to ensure proper running clearances.

There has been no recurrence of an engine uncontained failure leading to separation

was clear and dry with little or no wind and the temperature was 35°C. First evidence of the No. 1 engine inlet cowl contacting the runway was at three thousand feet. Spatters of molten aluminium were first noted at above five thousand feet from approach end. The aircraft stopped ten thousand feet from approach end slightly to left of center. The No. 1 engine was in a near vertical position. The engine had rotated around the mid spar attach points with the nose cowl resting on the runway and the exhaust plug and engine tail pipe jammed against the wing lower surface. The No. 1 strut upper link forward attach fuse pin was sheared. Pieces of fractured fuse pin remained in the upper link forward clevis fitting and associated strut attach lug. The aft end of the diagonal brace was detached from its associated fitting on the lower wing skin and the associated fuse pin was completely missing, and could not be found. Failure of these two strut attach points allowed the front of the engine to drop, contacting the runway. All equipment in the No. 1 strut sail boat area was destroyed by impact with strut aft bulkhead, engine exhaust pipe, tail cone and subsequent fire.

The No. 1 engine fuel supply line separated at the wiggins fitting between strut bulkhead and wing front spar. All wire bundles to the engine appeared to have been broken due to tension caused by the strut rotating to a vertical position. All leading edge flaps and leading edge fiberglass panels severely burned inboard and outboard of No. 1 strut. The outboard end of the outboard trailing edge flap was severely burned. The outboard flap track fairing was totally consumed by fire. The inboard end of the outboard aileron was severely burned. The outboard spoilers 1 and 2 and the trailing edge fiberglass panels inboard and outboard of the No. 1 strut was severely burned. The left wing tip was drooping down outboard of the No. 1 strut at about 15 degrees. There was evidence of extreme heating and warping of upper wing skin above the No. 1 strut. The upper wing skin was pulled loose from the forward and aft spar webs outboard of the No. 1 strut. Vent stringers were split open longitudinally. All upper wing skin rivets were pulled through the skin in the area of the surge tank. The lower wing skin was scorched in area of surge tank.

Analysis

In brief summary, the fuel from the ruptured fuel line and hydraulics in the strut were ignited by the hot engine and exhaust, followed by auto ignition of residual fuel in the reserve and surge tanks due to external heating. Fuel supply to the fire was terminated prior to the aircraft coming to rest and flammable wing and subsystem material continued to burn until extinguished by ground personnel.

Following forward strut pin failure and engine dropping nose down:

- Fuel is discharged at approximately 100 gpm into air stream prior to engine spar valve closure due to fuel line separation from front spar coupling. Fuel is washed under and possibly over wing and into leading edge cavity due to both forward speed of aircraft and due to thrust reverser air from engine.
- Due to engine exhaust/tailpipe being rotated up which forced diagonal brace into the hydraulic reservoirs in strut aft fairing, reservoir is crushed and 10 gallon (U.S.) hydraulic fluid is released.
- Fuel and/or hydraulic fluid is ignited on hot engine tail cone/nozzle.
- Hot engine exhaust gases and/or fuel fire heat the lower surface of reserve tank. Reserve tank is empty, but air is heated in excess of fuel AIT (auto ignition temperature). Residual undrainable fuel is approximately one U.S. gallon.
- Heated air or burning fuel vapor reaches surge tank through the reserve tank vent line. Fire initiates in surge tank due to residual fuel vapors and temperature in

by a closing failure of the shutoff valve. Damage (collateral) of the piping following the pylon detachment could be the cause of the leak. The exact location of the leak could not be detected.

During all of the descent at speeds greater than 220 kt, it is probable that the fuel leak carried on without the fuel catching fire, as the conditions for ignition (depression of the upperwing, speed....) were not achieved and the vaporized fuel was not in contact with the electrical short-circuits of the damaged cabling loom located on engine No.3 leading edge. These conditions changed during the last turn as a consequence of the semi-extension of the flaps. The speed reduced (between 220 and 190 kt), the depression on the upper wing decreased and the turbulence increased. Then, it was possible that under the effect of the electric arcs of the short-circuits quoted above, the fuel ignited, as the conditions of the kerosene-air mixture became optimal for burning. The fire was violent as the condition of the upper wing demonstrated, particularly at the trailing edge. This intense fire had destroyed the trailing edge as well as the flaps and left evidence of overheating over the whole of aft part of the right fuselage side. The air traffic controller advised that the right wing was on fire at 08:33:28 hrs and the landing touchdown occurred at 08:35:35 hrs. Consequently, the right wing fire lasted for at least two minutes.

The accident report did not provide a good rationale for the explosion in the No.4 main tank. It is believed that during the intense fire the wing structure may have weakened and fire progressed to the air-fuel mixture in the tank.

Mitigating Action Taken

An airworthiness directive was issued to inspect the pylon/strut mid-spar fittings at 1500 hours or 600 cycles.

Lightning Strike Events

- | | | |
|----|-----------------------------------|---------------------------------------|
| 5. | Date: 8 December 1963 | Flight phase: Holding |
| | Aircraft: Boeing 707 | Tank type: Wing (reserve) tank |
| | Location: Elkton, Maryland | Fuel type: Jet A / JP-4 mix |

The flight was in a holding pattern at 5,000 feet awaiting an instrument approach to Philadelphia airport from Baltimore, when it was struck by lightning. Immediately thereafter, the aircraft was observed to be on fire. A large portion of the left wing separated in flight and the aircraft crashed in flames near Elkton, Maryland. The probable cause was lightning induced ignition of the fuel/air mixture in the No.1 reserve fuel tank with resulting explosive disintegration of the left outer wing and loss of airplane control.

Fuel onboard at the time of the accident was approximately a 68% Jet A / 32% JP-4 by volume mix. It was estimated that fuel temperatures were 42°F in the reserve tank and 46°F in the main tanks. Considering all factors it was concluded the fuel vapors in all tanks were within the flammability limits. Multiple lightning-strike marks were found on the left wing tip. Although much effort was expended, the physical evidence failed to disclose the precise mechanism of ignition which triggered the explosion in the left reserve fuel tank.

Mitigating Action Taken

wing. Extreme engine oscillations developed as a result of the wing box damage. The loss of the rear box structure allowed the wing to twist torsionally and to deflect up and down about the rear spar. The first objects along the flight path were units from the inside of No.1 fuel tank. The three fire areas within the left wing contained electrical devices. The highest level of residual magnetic field was along the rear spar aft of the No.1 tank. A motor that operates a fuel valve normally mounted in this position was never found. Damage to the fuel tank access doors could only result from pressure from inside. No structural loads were applied to these doors. The 28Hz oscillations superimposed on the power line were in the area of the third harmonic of the wing oscillations (9Hz) which were attributed to engine fan rub in the early service history of the 747. The inertial damage to the extreme wing tip (H.F. antenna and coupler) could result only if the inboard section of the wing tip was still attached to inner wing. Throttle lever vibration in synchronization with the wing oscillations was observed during previous incidents. The damage to the wing tip cannot be caused by gust loads or aerodynamic loads. They were due to wing oscillations. The wing oscillations were the result of rear box failure. The deformation to rib WS 1168 was caused by pressure loads prior to its departure from the wing along with the jettison fuel line. The flight control difficulty mentioned on the CVR was probably related to the outer wing damage. The crossover vent duct for the forward outboard end of the No.1 tank was severely fire damaged, and the aft end was never recovered.

Fuel Tank Flammability Evaluation Results

Based on these calculations of the fuel and ullage conditions, the fuel/air mixture in portions of the ullage may be such as to permit ignition at the time of a descent through 10,000 feet.

Analysis

Consensus of the highly specialized investigation team was that an explosion occurred at or near the aft outboard corner of the No.1 Tank.

Conclusion from the Accident Report

After analyzing all of the available evidence, it is concluded that the most probable sequence of events which culminated with multiple structural failures and separation of the wing began with an ignition of the fuel vapors in the No.1 fuel tank. The damage to the structure in the area of the tank provided positive indications of an explosion. The possibility that the explosion was a secondary result of an initial structural failure caused by excessive aerodynamic forces developed during high velocity gusts and turbulence cannot be completely dismissed; however, the evidence and the probabilities of an aircraft encountering these unique environmental conditions make this hypothesis less supportable.

Mitigating Action Taken

A design change was incorporated that basically improved bonding (electrical grounding) where plumbing passes through the wing spar to further dissipate the voltage difference.

There has been no recurrence of a lightning strike related explosion to this model airplane or any other fleet airplane since this event in more than 246 million flights.

any of the servicing personnel. Over-pressure damage to the aircraft's No.2 fuel tank was extensive but minor in nature.

The aircraft was being readied for its next departure. Besides the refuelling operations, other activity around the aircraft included baggage loading and de-icing operations. Some light snow was being stirred around by a wind that was blowing from the left to the right wing at 18 knots with gusts to 24 knots. The outside ambient temperature was +8°F.

After about 5 minutes of fuelling with kerosene type A (Jet A) , a harsh muffled explosion shook the aircraft with a large white cloud of smoke or vapor issuing from the LH wing root area and continuing for about 30 seconds. The outboard boost pump cavity access door was split in two with half flying across the apron and half still dangling from the opening. Fuel was leaking from the cavity area in a stream about the size of a pencil diameter. The fueller immediately dropped the "dead man" switch and closed both fuelling nozzles. The fire department was then summoned, and they hosed down the area.

Subsequent examination of the aircraft revealed minor exterior physical damage, most noticeable being the blown-off access door, collapsed and fractured number 2 tank LH fuel boost pump cavity housing, and popped rivet heads on the number 2 tank LH upper skin area. Interior physical damage was quite extensive within the number 2 fuel tank. Both the No.1 and No.3 tanks were undamaged. Evidence of soot deposits were found within the left and right hand surge tanks, the number 2 fuel tank, and at each wing tip fuel tank vent scoop area.

The investigation that followed the incident indicated that the probable cause of the explosion was delivery by the ground fuelling system of highly charged fuel into the airplane. However, the investigation was unable to pinpoint the exact source of ignition that triggered the combustion of the fuel vapor. The evidence is very strong, however, that the source of ignition was static discharge internal to the number 2 fuel tank.

Time of day was 6:18 am. Fuel temperature was 31°F. Flash point of samples was: Tank #1-119°F, Tank #2 - 118°F, Tank #3 - 124°F and the Storage tank from which the fuel was loaded was 121°F.

At the time of the event the following airplane systems were operating: APU, all navigation lights on, No.2 tank boost pumps on and all crossfeed valves open.

The duration of the fuelling was approximately 5 minutes with No.2 tank 32% full.

Mitigating Action Taken

The paper element filter separators in the ground refuelling equipment were replaced with filters that did not create electrostatic charging.

There has been no recurrence of a refuelling related event to this model since changes were made.

