

Halon Replacement, Aircraft Engine Nacelle

HFC-125 Over-pressure Observations at the FAA Technical Center

Presented to: International Aircraft Systems Fire
Protection Working Group

By: On behalf of :

Doug Ingerson

Federal Aviation Administration

WJ Hughes Technical Center

Fire Safety Branch

Atlantic City Int'l Airport, NJ USA


tel : 609-485-4945

email : Douglas.A.Ingerson@faa.gov

Date: 23May2013



Federal Aviation
Administration



Presentation Overview

- **Review of testing with HFC-125 at the FAA Technical Center**
- **Provide information regarding test environments and behaviors**
- **Creates map of the *over-pressure* behavior of HFC-125 as related to test condition**



Identifying Pertinent Tests

- **Cargo compartment tests**
 - 8July1997
 - 18Sep1997
- **Pressure vessel tests, Dec 2003 – Jan 2004**
- **Nacelle fire simulator tests, Dec 2004**



Cargo compartment, 8 July 1997

- B727 lower-lobe, forward cargo compartment, $\approx 11 \text{ m}^3$
- Compartment characteristics
 - “somewhat” modified aircraft structure
 - “empty” volume
 - functionally-porous; “leakage” flow(s) possible
 - no proximal forced ventilation
- Fire threat = exploding aerosol can simulator (EACS), 1997-variant
 - EACS filled with $\approx 91 \text{ g}$ propane and $\approx 71 \text{ g}$ isopropyl alcohol
 - pressurized by heating then discharged into compartment
 - ignited by a “small” pan of burning hydrocarbon fuel
- HFC-125 use = none

To review this test and the 1997-variant EACS, see Marker (1998) :
Marker, T., “Initial Development of an Exploding Aerosol Can Simulator,”
FAA report DOT/FAA/AR-TN97/103, April 1998.



**viewing outside
the cargo
compartment**

15:42 ←

ignore this time/date stamp
(time/date of visual record duplication)

end of compartment
with EACS mounted
externally to bulkhead
(EACS end)

end of compartment with one
camera externally located at
bulkhead to view compartment
interior during EACS activation
(camera end)

hooded camera on tripod to
view compartment interior

wooden fence

- Subsequent images for this test were lifted from a duplicated digital visual history captured at 30 frames/second.
- Frame numbers are sequential; can be used to determine inter-frame durations
- Frame #10 links the different visual histories to the same point in time.



03/29/2013 07:15:42


viewing outside
the cargo
compartment



view of the site just before destruction begins

frame 006

03/29/2013 07:15:42
Camera04



bulkhead separating from the
compartment, negatively affecting
the camera viewing the interior

frame 010

note *transient* skin flexure
at floor beam plane

03/29/2013 07:15:49
Camera04



EACS and its mounting
panel separated from
the compartment structure

frame 218

camera viewing
the wooden fence

03/29/2013 07:15:42
Camera04



frame 020

OUTCOME :
Compartment suffered notable pressure-related damage resulting from the use of the 1997-variant EACS.




Federal Aviation
Administration

viewing inside the cargo compartment



frame 006

- ignition source is burning
- EACS injection plume not yet visible



frame 017

- viewing the wooden fence from this camera's new location




frame 007

- 1st video frame of the EACS injection plume



frame 010

- the bulkhead the camera is peering through is beginning its partial separation from other compartment structure



frame 008

- EACS injection plume expanding



frame 009

- plume expanding and starting to burn



Cargo compartment, 18Sep1997

- Bldg 275's DC-10 lower-lobe cargo compartment, $\approx 67 \text{ m}^3$
- Compartment characteristics
 - “notably” modified aircraft structure; sheet metal boundary
 - approximately a 70% empty volume
 - forced-ventilation moved through fuselage around compartment
 - “leakage” flow occurred through compartment; 102 mm dia duct exhausted compartment to atmosphere
- Fire threat = 202 kg of cardboard boxes filled with shredded-paper
 - thermal ignition source contained in 1 box and buried inside pile
 - fire propagated from initial box throughout pile during ≈ 90 minutes
- HFC-125 use
 - a “high”-rate injection occurred upon smoke detector activation
 - upon deficient concentration from initial injection, metered HFC-125 injection established to maintain concentration

To review this test, see Blake, et al. (1998) :


Blake, D., Marker, T., Hill, R., Reinhardt, J., Sarkos, C., "Cargo Compartment Fire Protection in Large commercial Transport Aircraft," FAA Report DOT/FAA/AR-TN98/32, July 1998.




Federal Aviation
Administration

Cargo compartment, 18Sep1997


Dimensioned View,
Cargo Compartment



Schematic View,
Ventilation Flow Paths



Schematic View,
Compartment Loading




Modified images of figures 1 & 2, p.17, taken from Reinhardt, J., Blake, D., Marker, T., "Development of a Minimum Performance Standard for Aircraft Cargo Compartment Gaseous Fire Suppression Systems," FAA Report DOT/FAA/AR-00/28, September 2000



Federal Aviation
Administration

Cargo compartment, 18Sep1997

Test History, O₂ and HFC-125 Concentrations,
Dual-point Temperature



Similar to figure 2, p.6, of :

Blake, D., Marker, T., Hill, R., Reinhardt, J., Sarkos, C., "Cargo Compartment Fire Protection in Large commercial Transport Aircraft," FAA Report DOT/FAA/AR-TN98/32, July 1998.

OUTCOME :

The compartment's "hot" gas layer experienced a notable thermal excursion, a 2ND volume of fire, attributed to HFC-125. Subject authors reported not observing such things previously. Compartment suffered no pressure-related damage.



Federal Aviation
Administration

Pressure Vessel, Dec2003-Jan2004

- Bldg 276's pressure vessel, $\approx 11 \text{ m}^3$
- **Compartment characteristics**
 - not aircraft structure; “thick” plate/cast steel
 - “empty” volume
 - no ventilation and pressure-tight; i.e. no leakage
- **Fire threat = EACS, 2003-variant**
 - filled with $\approx 90 \text{ g}$ propane, $\approx 270 \text{ g}$ ethyl alcohol, and $\approx 90 \text{ g}$ water
 - pressurized by heating then discharged into compartment
 - ignited by alternating-current (AC) electrical arc
- **HFC-125 use**
 - injected into compartment then compartment contents were mechanically stirred
 - homogenous mixture established prior to fire threat activation


To review this testing, see Reinhardt (2004) :

Reinhardt, J., “Behavior of Bromotrifluoropropene and Pentafluoroethane When Subjected to a Simulated Aerosol Can Explosion,” FAA report DOT/FAA/AR-TN04/4, May 2004



Federal Aviation
Administration



Pressure Vessel, Dec2003-Jan2004



Views,
Pressure
Vessel

EACS

This EACS schematic is figure 8, p.15 taken from Reinhardt, J., "Minimum Performance Standard for Aircraft Cargo Compartment Halon Replacement Fire Suppression Systems," DOT/FAA/AR-TN03/6, April 2003




This pressure vessel schematic is a modification of figure 1, p.6 taken from Reinhardt, J., "Behavior of Bromotrifluoropropene and Pentafluoroethane When Subjected to a Simulated Aerosol Can Explosion," FAA report DOT/FAA/AR-TN04/4, May 2004



Pressure Vessel, Dec2003-Jan2004

Some of the Test Histories for Various Conditions,
Total Pressure, Pressure Vessel Interior



A modified image of figure 2, p.6,
taken from :

Reinhardt, J., "Behavior of Bromotrifluoropropene and Pentafluoroethane When Subjected to a Simulated Aerosol Can Explosion," FAA report DOT/FAA/AR-TN04/4, May 2004

OUTCOME :

Compartment experienced repeated and notable over-pressures, which exceeded the result from the 2003-variant EACS alone. $\approx 11\%v/v$ HFC-125 threshold related to over-pressure occurrence. Compartment suffered no pressure-related damage.



Nacelle Fire Simulator, Dec2004

- Bldg 205 nacelle fire simulator (NFS), $\approx 4 \text{ m}^3$
- Compartment characteristics
 - not aircraft structure; rolled sheet metal & “thin” plate steel
 - “empty” volume
 - has 1 atmospheric gap (duct interface); $\approx 0.7 \text{ m}^2$ (6 ft²); the gap is typically at negative pressure, drawing in test bay air
 - forced ventilation, flow $\approx 0.5 \text{ kg/s}$ @ 121°C, average speed just upstream of the flame fronts $\geq 1.2 \text{ m/s}$ (increases in exhaust nozzle)
- Fire threat = atomized spray fire, $\approx 563 \text{ g}$ sprayed over 45 sec
 - JP-8 or Mil-PRF-23699 lubricating oil (MJO2)
 - ignited by AC electrical arc; reignition by the same arc or “hot” surface (reignition event is created, intentional, & typical)
 - fuel sprayed during flame extinction duration; flame extinction due to the presence of HFC-125
- HFC-125 use = a single, initial “high”-rate injection


To review this testing, start at

<http://www.fire.tc.faa.gov/systems/sysarchive.stm>, then find the link within the Feb 2005 (2/05) Systems Fire protection Working Group meeting for “2. Engine Nacelle Halon Replacement (20MB Zip file)”, and download.



Nacelle Fire Simulator, Dec2004

NFS ELEVATION SCHEMATIC






$$A = \pi * s * (R + r)$$

$$= \pi * 10 * (17 + 11)$$


$$= 880 \text{ in}^2 \approx 6 \text{ ft}^2$$

VENT SURFACE
AREA, DUCT
INTERFACE



Federal Aviation
Administration

Nacelle Fire Simulator, Dec2004



OUTCOME :

Two of 16 total tests over-pressurize. Over-pressures characterized as "minor" smoke quantity discharged into test bay through the duct interface/atmospheric gap. Fire extinction behaved typically within test section. No structural damage.



Nacelle Fire Simulator, Dec2004

Providing images from 2 other tests; provides somewhat of a relative understanding...

- 2 sequential frames (30 frames/sec), analogous testing with 2-BTP instead of HFC-125, Sep 2004
- 1 frame, analogous testing with CF_3I , Sep 2006

OBSERVATIONS COLLECTIVELY INDICATE COMPLEXITIES EXIST AT THE DUCT INTERFACE, WHICH AFFECT DIFFERENT SUBSTANCES DIFFERENTLY...



Summarizing Pertinent Tests

- **B727 cargo compartment**
 - “severe” pressure-related damage to altered aircraft structure
 - “near-instant” duration propane/alcohol fire threat
 - without forced ventilation with leakage
 - without HFC-125 use

- **DC-10 cargo compartment**
 - no pressure-related damage to altered aircraft structure
 - “long” duration cellulosic fire threat
 - without forced ventilation with leakage
 - HFC-125 “high”-rate injection and metered delivery



Summarizing Pertinent Tests

- **Pressure vessel**

- no pressure-related damage to non-aircraft structure
- “near-instant” duration propane/alcohol fire threat
- without forced ventilation and without leakage
- varied HFC-125 use; all premixed homogenous HFC-125/air

- **NFS**

- no pressure-related damage to non-aircraft structure
- “short” duration turbine fuel/lubricating oil spray fire threats
- with forced ventilation and leakage
- HFC-125 “high”-rate injection delivery



Summarizing Pertinent Tests

Date(s) of Testing	Number of Tests		Test Compartment Descriptions			Fire Threat Descriptions			HFC-125 Use Descriptions	Noteworthy Atypical Behavior
	Total	Atypical	Type, Volume	Pre-fire Ventilation	Leakage Possible ?	fuel package	combustion mode	life span		
08Jul1997	1	1	"cargo", altered aircraft structure, $\approx 11 \text{ m}^3$	buoyant	yes	propane, isopropyl alcohol	evaporative boiling to diffusion flames	$\approx 0.003 \text{ min}$ (a)	none	compartment overpressure with structural damage
18Sep1997	1	1	"cargo", altered aircraft structure, $\approx 67 \text{ m}^3$	buoyant	yes	cardboard boxes filled with shredded paper (cellulosic)	pyrolysis to diffusion flames	$\approx 90 \text{ min}$	"high-rate" and metered injections; all accomplished during the fire	fire in compartment's "hot" gas layer without pressure-related structural damage
07-14Jan2004	8	4	pressure vessel, non-aircraft structure, $\approx 11 \text{ m}^3$	buoyant	no	propane, ethyl alcohol (water included in EACS contents also)	evaporative boiling to diffusion flames	$\approx 0.03 \text{ min}$ (b)	"high-rate" injection then compartment stir and soak; all completed before the fire	compartment overpressure without structural damage
09-21Dec2004	16	2	"engine", non-aircraft structure, $\approx 4 \text{ m}^3$	forced	yes	JP-8 or Mil-PRF-23699 oil	evaporative "boiling" to diffusion flames	$\approx 0.75 \text{ min}$	"high-rate" injection completed during the fire	smoke released to test bay through an atmospheric gap without structural damage

Notes :

(a) Lifted frame numbers from the visual record of the external "camera end" view. The duration is for the motion of the viewed compartment bulkhead from its initial position to the point of farthest separation and subsequent reversal in motion. The duration represents the pressure creation within the compartment; i.e. indicative of the reaction occurring.

(b) Taken from pressure vessel's pressure history, shown in figure 2/p.6 of Reinhardt (2004). Duration is from the start to peak of pressure history, indicative of the reaction occurring. Reaction completion indeterminate by pressure history as the pressure vessel fully retains pressure rise from the reaction, and associated decay is due to cooling.




Summarizing Pertinent Tests

- **Fire threat intensity appears significant**
 - EACS variants capable of psi-magnitude pressure increases
 - combusting NFS fuel sprays & paper-filled cardboard boxes create compartmental pressure increases of water-column magnitude
 - attributable to propane as 1 of its constituent fuels
 - expansion & vaporization upon release are the most active of these fuels
 - expansion & vaporization assist with dispersing other EACS contents
 - EACS >> NFS fuel sprays > paper-filled cardboard boxes
- **Compartment ventilation and leakage not so much**
 - NFS > cargo compartments >> pressure vessel
- **Considerations of structural similarity with aircraft**
 - Cargo compartments > NFS >> pressure vessel



Summarizing Pertinent Tests



Summarizing Pertinent Tests

- **Suggested over-pressure considerations**
 1. The type of fire present
 - energy availability – fuel type (propane, Jet-A, cellulose), quantity
 - rate of energy release – state/phase, vapor pressure, subdivision
 2. HFC-125 use
 - quantity
 - fire/HFC-125 interaction? – pre-/post-fire injection, resident duration
 - state? – “cold”-/”hot”-soaked at discharge
 3. Aspects of the compartment that attenuate over-pressure
 - ventilation – dilutional flow and cooling, over-pressure bleed pathway
 - ability to “leak” – over-pressure bleed pathway
 - structural composition – ability to withstand over-pressure
 - filled/cluttered volume? – quenching? fluid flow & mixing dynamics?



NFS Appendix Information


- Additional information is here provided to permit further review of the complexities of the NFS testing, which exceed the need-to-know for this meeting presentation.
- This information is provided for those having further interest in this topic.



Nacelle Fire Simulator, Dec2004

SCHEMATIC VIEW OF SOME PERTINENT NFS THERMOCOUPLES


Name of Thermocouple or Sensor in Graph	Description of Thermocouple or Sensor
sen/FRX botl p/t	pressure signal from pressure transducer sampling inside firex bottle
sen/Inlt HWA	flow speed signal from hot-wire anemometer at NFS inlet
TCel Temp (TC)	air temperature in the test bay
tst/470/t/csfc_06	surface temperature of the NFS core, sta470/06:00
tst/483/t/csfc_12	surface temperature of the NFS core, sta483/12:00
tst/490/t/spr_f.1	temperature of the fuel feeding the NFS spray fire
tst/495/t/c_int	air temperature inside the NFS core, sta 495
tst/514/t/ex11:30	surface temperature of the NFS shell, sta514/11:30
ave_sta453lwr	average air temperature in the test section annulus, sta 453/lower lobe (4 TCs)
ave_sta453upr	average air temperature in the test section annulus, sta 453/upper lobe (4 TCs)
ave_sta551lwr	average air temperature in the test section annulus, sta 551/lower lobe (6 TCs)
ave_sta551upr	average air temperature in the test section annulus, sta 551/upper lobe (6 TCs)



Nacelle Fire Simulator, Dec2004

GRAPH OF THE TYPICAL NFS ENVIRONMENT DURING A FIRE EXTINGUISHMENT TEST

Test 04c15-10, overpressure at duct interface
ventilation rate ≈ 1.0 lbf/s @ 250°F
5.8 lbf HFC-125 injected through "cert" plumbing
spray fire fuel was a lubricant (Mobil Jet Oil II)



- Test 04c15-10 is here shown, 1 of 2 tests that over-pressurized the NFS duct interface
- Thermal variations seen just after the firex discharge are associated with the HFC-125 injection into the NFS environment
- 5.8 lbf HFC-125 extinguished this fire for 4.15 sec.

$T(^{\circ}C) = 5/9 * (T(^{\circ}F) - 32)$
1 psi = 6.9 kPa


@ 1g, 1 lbf has a mass = 1 lbf, 1 kg = 2.205 lbfm



Federal Aviation Administration

Nacelle Fire Simulator, Dec2004

GEOMETRY OF THE DUCT INTERFACE (atmospheric gap)




from KC46-MyPreps-variousCALCS.xls, NFS duct intrface dims c



Nacelle Fire Simulator, Dec2004

HFC-125 CONCENTRATION HISTORIES, 5.8 LBF INJECTED

- measured without fire present
- test # 2004c06-12
- 12 sample points dispersed about the sta502 spray flame front per MPSe rev03
- only 8 sample points shown in this graph
- all sample points are in the free stream




Pre20130523.xls; H125 gas/ANA 04c06-12 c01



Nacelle Fire Simulator, Dec2004

HFC-125 CONCENTRATION HISTORIES, 5.8 LBF INJECTED



- measured without fire present
- test # 2005321-12
- 12 sample points used, 3 relocated within the NFS exhaust nozzle and 1 inside the red exhaust duct
- all sample points EXCEPT “sta563/1200-ucs” are in the free stream



Nacelle Fire Simulator, Dec2004

HFC-125 CONCENTRATION HISTORIES, 5.8 LBF INJECTED

- measured without fire present
- test # 2005321-12
- 12 sample points used, 3 relocated within the NFS exhaust nozzle and 1 inside the red exhaust duct
- all sample points EXCEPT “sta563/1200-ucs” are in the free stream



Pres20130523.x.lis, H125.grs/ANA 05321-12.c02

