

# Class E Cargo Compartment Smoke Detection



Federal Aviation  
Administration



Presented to: Sixth Triennial Aircraft Fire and  
Cabin Safety Conference. Atlantic City, NJ

By: Dave Blake. FAA Technical Center. Atlantic  
City, NJ. Email: [Dave.Blake@faa.gov](mailto:Dave.Blake@faa.gov)

Date: October 25-28, 2010



*UPS DC-8  
Feb. 7, 2006  
Philadelphia, PA*



**Class E Cargo Compartment Smoke Detection and Active ULD Testing**

Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010



**Federal Aviation  
Administration**



**Class E Cargo Compartment Smoke Detection and Active ULD Testing**

Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010



**Federal Aviation  
Administration**

# Cockpit Voice Recorder Transcript<sup>1</sup>

2333:44 Aircraft cleared to descend from FL 330 to FL 240

2334:39 “Smell like wood burning”

2335:40 “It’s pretty strong now”

2335:54 Cockpit door opened “It’s more in the back”

2338:39 One pack turned off

2343:18 “Fume evacuation”

2343:27 Packs on max flow, recirc fan off

2347:59 Cockpit door opened again “It’s definitely stronger in the back. No haze or smoke when I shined my light back there” At FL 40

2354:42 “Cargo smoke detectors on” At FL 20

2355:48 Landing gear down

2355:57 “Lower cargo compartment aft smoke detectors on”

2359:00 Touch down

2359:02 “Smoke in cockpit”

2359:45 End of transcript. Crew evacuated through L1 door

<sup>1</sup> Source: NTSB Accident Report



## NTSB Recommendation A-07-98 to the FAA.

**“Ensure that the performance requirements for smoke and fire detection systems account for the effects of cargo and cargo containers on airflow around the detection sensors and on the containment of smoke from a fire inside a container and should establish standardized methods of demonstrating compliance with those requirements. (A-07-98) “**





# 727 Freighter

Main Deck Airflow approximately one air change every 5.1 minutes (11.8 air changes/hour). Air from one pack supplied with APU bleed air.






**4 Aspirated Photoelectric Smoke Detectors (94-96% light transmission/ft alarm point)**



**Certified to one minute detection time (FAR 25.858)**



## Class E Cargo Compartment Smoke Detection and Active ULD Testing


Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010



Federal Aviation  
Administration





727 Freighter 88" cargo container positions



**Class E Cargo Compartment Smoke Detection and Active ULD Testing**


Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010




**Federal Aviation  
Administration**

# 727 Main Deck



**727 Main Deck Detection Time Difference (Empty minus Full)**



# 747SP Below Floor Compartment

**Ventilation airflow provided one air change approximately every 6 minutes (10 air changes per hour). Air source was 2 air conditioning packs supplied with bleed air from the APU**



2 Aspirated photoelectric smoke detectors. Calibrated to alarm at 90.6 +/- 1 percent light transmission per foot.



Class E Cargo Compartment Smoke Detection and Active ULD Testing


Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010



Federal Aviation  
Administration

# 747SP Aft Cargo Compartment




## Class E Cargo Compartment Smoke Detection and Active ULD Testing

Six Triennial Aircraft Fire and Cabin Safety Conference

October 25-28, 2010



Federal Aviation Administration



## Class E Cargo Compartment Smoke Detection and Active ULDT Testing

Six Triennial Aircraft Fire and Cabin Safety Conference


October 25-28, 2010



Federal Aviation  
Administration




# 747 Time of Initial Alarm Regardless of Duration




# 747 Time of Initial Alarm Regardless of Duration

Average detection time for all positions tested is 13 seconds faster for the fully loaded compartment.



### 747 Lower Aft Compartment Sustained Detection



**Final report has been published and is available on the  
FAA Fire Safety website at:**

**[www.fire.faa.tc.gov](http://www.fire.faa.tc.gov)**

