Difficult Areas For Burnthrough Implementation

Objective

- Include methods of compliance in the AC for all configurations in airplanes.
 - Same safety standard worldwide
 - Same safety standard from all airframe manufacturers
 - Address certification issues early on

Overview

- Testing Issues
- Unique Configurations
- Summary

Testing Issues

- The Advisory Circular gives detailed instructions for testing burnthrough designs when blankets are installed between and over frames. Depending on the airplane 20% to 80% of insulation cannot match configurations currently in the AC.
- Minimal direction is given for unique configurations that cannot be attached as stated in the AC currently.
- Many configurations do not fit the test apparatus.

- There is not an identified method to certify unique designs to the flame penetration test
- Attachments in some areas are unable to meet burnthrough requirements
- Examples
 - Upper cheek Main deck floor beam and frame intersection
 - Main Deck Entry Doors and Hatches
 - Blankets Surrounding Main Deck Entry Doors
 - Lower Lobe Cargo Doors
 - AOE doors and linings
 - Airstair door
 - Aft Pressure Bulkhead
 - Nose Bulkhead
 - Cargo Bulkhead
 - Nose wheel well bulkhead/Bilge
 - Over-frame support beams
 - Sloping sidewalls
 - Bilge
 - EE Bay Hatch and walkway





- Upper cheek Main deck floor beam and frame intersection
- Situation:
 - Not able to clamp over frames due to floor beams
 - No other attachment method known that meets rule
 - No method for testing



- Main Deck Entry Doors and Hatches
- Situation:
 - Contain blankets that are installed into pockets, retained with bond-on pins or hook and loop
 - No overlap possible must maintain door functionality.
 - Cannot add holes for screw though pins
- Allow burnthrough materials with best design solution no testing required





- Blankets Surrounding MainDeck Entry Doors
- Situation:
 - Unique structure around doorways does not allow for use of screw-through pins or clamps
 - Blankets are attached to structure with hook and loop
 - Overlap of blankets is not possible must maintain door functionality.



- Lower Lobe Cargo Door
- Situation:
 - Foam is attached to outboard side of cargo liner with adhesive.
 - Insulation attached to door with hook & loop
 - No method for testing





- Automatic Over-wing Exit(AOE) doors and linings
- Situation:
 - Unique structure around doorways does not allow for use of screw-through pins or clamps
 - Blankets installed on liner with double back tape.




- Airstair Door
- Situation:
 - Unique structure around doorways does not allow for use of screw-through pins or clamps
 - Foam pad glued to aluminum skin (shown left of door) and is attached to inboard surface of door using velcro.





- Aft Pressure Bulkhead
- Situation:
 - No frames to attach to
 - Stringers will burn away in less than 4 minutes leaving no method of attachment
 - No method for testing



- Nose Bulkhead
- Situation:
 - Blankets are attached using hook and loop or bond on attachments
 - Not able to use clamps around perimeter locations



■ Nose Bulkhead





- Cargo Bulkhead
- Situation:
 - Blankets are attached using hook and loop or bond on attachments
 - Not able to use clamps around perimeter locations



- Nose wheel well bulkhead/Bilge
- Situation:
 - Unique structure does not allow for use of screw-through pins or clamps
 - No testing method known



- Over-frame support beams
- Situation:
 - Certification is undefined due to slits needed to overlap frame.





- Sloping sidewall
- Situation:
 - Blankets do not overlap frame because of cargo liner attachment
- Allow cargo liner as part of the burnthrough configuration



- Bilge
- Situation:
 - Blankets do not overlap frame
 - Airplane geometry requires splice at frame skin intersection
 - Bilge frame up to 2' deep
 - No method for testing





- EE Bay Hatch and walkway
- Situation:
 - Unique structure around hatches does not allow for use of screw-through pins or clamps
 - Foam bonded or attached with velcro to interior surface of EE bay hatch and walkway





- Nose Wheel Well
- Situation:
 - No method of testing large blankets in test rig
 - No method of testing box corners
 - No attachment method known for this geometry

Summary

- Many areas of the airplane have blanket configurations that are not depicted in the proposed scenarios of AC 25.856-2X
- Many airframe designs are not depicted in the proposed AC. Methods of testing these designs and attachments are not well defined.
- Certification method for areas not depicted in the AC is not well defined.