

# International Aircraft Materials Fire Test Working Group Meeting

## Seat Cushion Test Method Update

Presented to: International Aircraft Materials Fire  
Test Working Group

By: Tim Salter, FAA Technical Center

Date: March 6-7, 2013, Renton, WA



Federal Aviation  
Administration



# Previous Meeting Items


- **Completed stator and turbulator settings for seat cushion sonic burner**
- **Test results of stator with no igniters**
- **Introduction to flame retention head (FRH)**
- **Proposed standardized methods of leather seat cushion restraints**
- **Sonic burner seat cushion RR update**

# Summary for this Meeting


- **Information regarding flame retention head and overview of initial test data**
- **Status of leather seat cushion restraints**
- **Sonic burner seat cushion round robin**
- **Initial test results of TC readings using sonic burner compared to TC calibration unit results**

# Flame Retention Head (FRH)

- **Eliminates the need for a stator and turbulator**
- **Fits on end of burner draft tube with minimal modification**
- **Parts purchased from local heating supply store for less than \$50**
- **Initial testing showed potential for improved test result repeatability as compared to stator and turbulator configuration**




# Flame Retention Head (FRH)



- **Extremely low variation of temperature**
- **Less than 1°F variation of averaged temperatures**

# Flame Retention Head (FRH)




- Results from first tests using flame retention head

# Flame Retention Head (FRH)

- Initial tests show that increasing air inlet pressure tends to increase percent weight loss
- Currently testing different air pressures, fuel nozzle spray patterns, and internal burner settings
- Further testing is required to fine tune the burner and FRH before any conclusions can be made regarding the FRH's suitability as part of the seat cushion oil burner test

Cushion % Weight Loss using Flame Retention Head and Varying Inlet Air Pressure



# Leather Cushion Restraints

- **Industry has asked that a standardized method of restraining leather seats to the test frame be developed**
- **Work had been performed in the past, but no final conclusions were made**
- **Data has shown that there is not necessarily a correct or incorrect method of restraining leather cushions**
  - However, restraints should not impede the flame
- **A standardized restraint method used by all labs should increase test result repeatability**



# Leather Cushion Restraints


- **Items to consider**
  - Number of restraints
  - Spacing of restraints
  - Type of restraint (safety wire, hook and loop, etc.)
- **Goal**
  - Devise a method of restraint to maximize repeatability, but not overcomplicate restraint method in order to keep sample preparation time to a minimum

# Leather Cushion Restraints

## Restraint Example #1



## Restraint Example #2



# Leather Seat Cushion Restraints

- **There is currently a recommended method of leather seat restraint outlined in the handbook**
  - “More than one wire may be used to restrain leather seat components as long as the wires do not impede or redirect the flame.”
- **The main focus of recent work has been placed on development of the flame retention head for the seat cushion oil burner**
- **The subject of standardizing leather seat restraints will be revisited after FRH testing has been completed**
- **Open to suggestions for methods of restraint**

# Round Robin Update


- **Round robin ongoing since April 2012**
- **8 labs participating**
- **6 labs have completed testing**
- **FAA provided each lab with a fuel nozzle, burner setup instructions, and seat cushion test specimens**



# Current Seat Burner Settings

- **Sonic burner settings using stator and turbulator for use as Park burner replacement**
- **All depths are measured from the exit plane of the turbulator to the nozzle tip or front stator face**
  - Recommended Nozzle: Delevan 2.0 gal/hr 80° type B
  - Nozzle Depth: 3/16"
  - Stator Depth: 2 11/16"
  - Stator Angle: 0° (igniter centerline from vertical)
  - Turbulator: Notch will face bottom of tube (180°)
  - Air Pressure: 45.0 psi
  - Air Temperature: 40-60°F
  - Fuel Temperature: 32-52°F


# Seat Cushion Testing



- **3 of each cushion type tested per trial**

# Round Robin Update


## Fireblock Cushion Burn Lengths and Weight Loss Percent



- Lab at far left is FAA Technical Center

# Round Robin Update

## Dax Cushion Burn Lengths and Weight Loss Percent




- Lab at far left is FAA Technical Center



# Round Robin Update


## Airflex Cushion Burn Lengths and Weight Loss Percent



- Lab at far left is FAA Technical Center

# Round Robin Update

## Seat Cushion Percent Weight Loss Lab Comparison



	Fireblock	Dax	Airflex
Lab A	7.55	7.00	7.55
Lab B	11.02	5.85	8.52
Lab C	4.69	6.60	6.66
Lab D	6.50	8.97	7.93
Lab E	8.97	7.55	5.94
Lab F	10.18	7.10	6.45
Lab G			
Lab H			
<b>Avg</b>	8.15	7.18	7.17
<b>stdev</b>	2.37	1.05	0.98
<b>%stdev</b>	<b>29.09</b>	<b>14.57</b>	<b>13.72</b>

•FAA is Lab A

# Round Robin Update

- **Data indicates that current RR burner settings for the stator and turbulator configuration generate data comparable to Park burner weight loss and burn lengths**
- **Goal is to improve upon current repeatability of Park burner**
- **Decision was made to pursue development of the FRH based on repeatability shown in initial tests and data**

# Thermocouple Calibration

- **Looking further into TC degradation and changing temperature readings**
- **Thermocouple tend to indicate lower temperatures after repeated heat cycling which occurs during calibration of burner**
- **New calibration unit recently arrived at FAA Technical Center**
- **Determine effect of extreme heat cycling on thermocouples**
  - Possibly predict changes in temperature readings based on number of heat cycles?



# Thermocouple Calibration


- **First calibration run performing side by side comparison of two thermocouples**
- **Both 1/8" SS sheathed, grounded thermocouples**
  - One new and unused
  - One having been used in an extensive number of calibrations
- **Expectation is that used TC will read significantly lower temperatures than new TC**
- **Initial test showed almost no difference in temperature when tested at 1800 °F**




# Thermocouple Calibration

- Abbreviated time duration of actual tests shown below

**Maximum  $\Delta T = 3.56^\circ\text{F}$**



**Maximum  $\Delta T = 31.69^\circ\text{F}$**



# Thermocouple Calibration

- **Heat cycling appears to have an impact on the response time of thermocouples and not their ability to correctly read relatively steady state temperatures**
- **Extensively heat cycled TCs are unable to respond to rapid changes in temperature as seen when submerged in a turbulent burner flame**
- **Further testing planned to reduce or eliminate the problems associated with thermocouple reading degradation during calibration and testing**

# Planned Activities


- **Complete current round robin**
  - Finish gathering data from participating labs
- **Development of FRH**
  - Determine air pressure, fuel nozzle, internal settings
  - Plan for a future round robin using retention head
- **Finalize leather seat restraints**
  - Complete cushion testing
  - Share results at working group meeting
- **Thermocouple degradation**
  - Continue testing for methods of limiting inaccurate readings due to thermocouple heat cycling



# Error Due to Burner Misalignment


•Front View

**Correct**




•Front View


**Incorrect**



**Incorrect**




**Incorrect**




•Top View

**Incorrect**




**Incorrect**



•Top View

**Correct**



# Questions?

