

Airborne Fires from damaged electrical wiring - Recent AAIB investigations and Recommendations - Figures




Figure 2

Figure 1 - Detail, Concorde G-BOAC, 21 June 2003




Figure 2 - Detail, B737-300 G-LGTI, 30 July 2003



Figure 3 - Detail, B737-436 G-LGTI, 30 May 2003



Figure 4 - Detail, B737-436 G-DOCH, 8 November 2002



Figure 5 - Water hose damage, B737-436 G-DOCH