

DOT/FAA/CT-87/32

FAA Technical Center

Atlantic City International Airport
N.J. 08405

Current Fire Safety Design Aspects of Commuter Aircraft

Richard Clarke
Deborah Kane
Carla Stewart

EVENTS ANALYSIS, Inc.
Oakton, Virginia
22124

March 1988

Final Report

This document is available to the U.S. public
through the National Technical Information
Service, Springfield, Virginia 22161.



U.S. Department of Transportation
Federal Aviation Administration

NOTICE

This document is disseminated under the sponsorship of the U.S. Department of Transportation in the interest of information exchange. The United States Government assumes no liability for the contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the objective of this report.

1. Report No. DOT/FAA/CT-87/32		2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle CURRENT FIRE SAFETY DESIGN ASPECTS OF COMMUTER AIRCRAFT				5. Report Date March 1988	
				6. Performing Organization Code	
7. Author(s) Richard Clarke, Deborah Kane, Carla Stewart				8. Performing Organization Report No.	
9. Performing Organization Name and Address EVENTS ANALYSIS, Inc. 12101 Toreador Lane Oakton, Virginia 22124				10. Work Unit No. (TRAIS)	
				11. Contract or Grant No. DTFA03-86-C-00062	
12. Sponsoring Agency Name and Address U.S. Department of Transportation Federal Aviation Administration Technical Center Atlantic City International Airport, NJ 08405				13. Type of Report and Period Covered FINAL REPORT	
				14. Sponsoring Agency Code ACT-350	
15. Supplementary Notes					
16. Abstract <p>This study describes Fire Safety systems, cabin design and materials in cabin areas of ten common commuter aircraft. The aircraft were selected based upon a balance of current population and aircraft most commonly delivered. These aircraft represent 880 of 1100 commuter aircraft and probably will be the majority of the commuter fleet in the future.</p> <p>The trend in these commuter aircraft is increasing sophistication in application of materials similar to those in large commercial aircraft. Among the ten aircraft two are older, piston powered aircraft, simple in design and materials applications. Of the other larger eight aircraft, two are no longer delivered. Four newer and larger designs feature large, separate baggage compartments. Only two aircraft have overhead storage bins.</p> <p>One aircraft has a large interior with standing headroom. The others are much more compact, with interior storage limited to bins at the entry point. Thermoplastics and composite materials are used in the newer aircraft. Each aircraft originally was equipped with polyurethane cushions; currently, operators and manufacturers are protecting cushions with fire-blocking materials.</p> <p>Piston powered aircraft use gasoline cabin heaters and ram cooling airflow. The other eight aircraft are turboprop aircraft using engine bleed air for cabin heating and cooling. Six aircraft are unpressurized and four are pressurized. One new design has an optional oxygen system using oxygen generators; the other aircraft use cylinder stored oxygen.</p>					
17. Key Words Aircraft Fires, Commuter Aircraft, Aircraft Design, Aircraft Systems			18. Distribution Statement Document is available to the public through the National Technical Information Service, Springfield, Virginia 22161		
19. Security Classif. (of this report) Unclassified		20. Security Classif. (of this page) Unclassified		21. No. of Pages 76	
				22. Price	

PREFACE

This report was prepared by EVENTS ANALYSIS, Inc. under Contract No. DTFA03-86-C-00062 with the Federal Aviation Administration (FAA) Technical Center, where Gerald R. Slusher acted as Technical Monitor.

The EVENTS ANALYSIS, Inc. Program Manager has been Richard W. Clarke, with subcontract assistance by Phaneuf Associates Incorporated and by Veda Incorporated. The Phaneuf Associates subcontract manager has been Dr. Roger Phaneuf; Veda Incorporated's subcontract manager has been Mr. Ron Bentley. The following persons and organizations have been of noteworthy help in compiling information used during this study:

Mssrs. John Thompson and Dennis Lints, The deHavilland Aircraft Company of Canada
Mr. Charles Benn, owner/operator of the recently closed Woodbridge Airport, Virginia
Mr. Alan A. Driver, British Aerospace, Inc.
Mr. Raymond R. Gould, British Aerospace, Inc.
Ms. Teresa Allegri, Jetstream International Airlines
Mr. Tom Peay, Colgan Airways Corporation
Ms. Rebecca Garner, Cessna Aircraft
Mr. Bernard Castell, Embraer Aircraft
Mr. Tom Peck, Embraer Aircraft
Mr. Ken Morgan, Embraer Aircraft
Mr. Michael Gibson, Atlantic Southeast Airlines
Mr. Ray Crist, Piper Aircraft
Mr. Maurice Panther, Short Brothers (U.S.A.) Inc.
Mr. David Fox, Short Brothers, PLC
Mr. Jeff Robinson, Henson Airlines
Mr. Jim Cupp, Fairchild Aircraft Corporation
Mr. Curt Ward, Comair

TABLE OF CONTENTS

EXECUTIVE SUMMARY	Page ix
INTRODUCTION	1
Purpose	1
Background	1
THE POPULATION OF COMMUTER AIRCRAFT	2
Purpose	2
Approach	2
Population Research	2
Population Definition	3
COMMUTER AIRCRAFT MATERIALS AND SYSTEMS RESEARCH	7
Purpose	7
Methodology	7
Organization	7
COMPARTMENTATION	8
Baggage Areas	8
Stowage Compartments	21
Lavatories	21
Galleys	22
Firewalls	23
Partitions	23
MATERIALS	25
Lining Materials	25
Floor Coverings	29
Major Transparencies	30
Seats	31
Insulation	32
Wire Insulation	32
Fuselage Skin Thickness	34

SYSTEMS	45
Fire Detection	45
Fire Suppression	46
Hand Extinguishers	47
Oxygen Systems	48
Ventilation Systems	63
SUMMARY	75
APPENDIX - DISTRIBUTION LIST	

LIST OF FIGURES

Figure		Page
1.	Illustrations of the Ten Selected Commuter Aircraft. (2 pages)	5
2.	BAe Jetstream 3100 Compartmentation.	11
3.	Beech 99 Airliner Compartmentation.	12
4.	Beech 1900 Airliner Compartmentation.	13
5.	Cessna 402 Compartmentation.	14
6.	Twin Otter Series 300 Compartmentation.	15
7.	Embraer Bandeirante Compartmentation.	16
8.	Embraer Brasilia Compartmentation.	17
9.	Fairchild Metro III Compartmentation.	18
10.	Piper Navajo Compartmentation.	19
11.	Shorts 3-30 Compartmentation.	20
12.	BAe Jetstream 3100 Airliner Fuselage Skin Thickness.	35
13.	Beech 99 Airliner Fuselage Skin Thickness.	36
14.	Beech 1900 Airliner Fuselage Skin Thickness.	37
15.	Cessna 402 Fuselage Skin Thickness.	38
16.	Twin Otter Series 300 Fuselage Skin Thickness.	39
17.	Embraer Bandeirante Fuselage Skin Thickness	40
18.	Embraer Brasilia Fuselage Skin Thickness	41
19.	Fairchild Metro III Fuselage Skin Thickness	42
20.	Piper Navajo Fuselage Skin Thickness.	43
21.	Shorts 3-30 Fuselage Skin Thickness.	44
22.	BAe Jetstream 3100 Fire Detection, Fire Suppression, and Oxygen Systems.	51
23.	Beech 99 Fire Detection, Fire Suppression, and Oxygen Systems.	52
24.	Beech 1900 Airliner Fire Detection and Suppression Systems.	53
25.	Beech 1900 Airliner Oxygen Systems.	54

26. Cessna 402 Fire Detection, Fire Suppression, and Oxygen Systems.	55
27. Twin Otter Series 300 Fire Detection, Fire Suppression, and Oxygen Systems.	56
28. Embraer Bandeirante Fire Detection, Fire Suppression, and Oxygen Systems	57
29. Embraer Brasilia Fire Detection, Fire Suppression, and Oxygen Systems.	58
30. Fairchild Metro III Fire Detection, Fire Suppression, and Oxygen Systems.	59
31. Turbine powered Navajo Chieftain Fire Detection and Fire Suppression Systems.	60
32. Piper Navajo Oxygen System.	61
33. Shorts 3-30 Fire Detection, Fire Suppression, and Oxygen Systems.	62
34. BAe Jetstream 3100 Ventilation System.	65
35. Beech 99 Airliner Ventilation System.	66
36. Beech 1900 Airliner Ventilation.	67
37. Cessna 402 Ventilation.	68
38. Twin Otter Series 300 Ventilation System.	69
39. Embraer Bandeirante Ventilation System.	70
40. Embraer Brasilia Ventilation System.	71
41. Fairchild Metro III Ventilation System.	72
42. Piper Navajo Ventilation System.	73
43. Shorts 3-30 Ventilation System.	74

LIST OF TABLES

Table	Page
1. The Ten Most Common Commuter Aircraft based on FAA Census of Civil Aircraft -- 1984.	2
2. The Ten Most Common Commuter Aircraft based on Regional Airline Association and FAA Data -- 1986.	3
3. <u>World Aviation Directory</u> Totals of Commuter Aircraft Deliveries for 1984, 1985 and January-October 1986.	3
4. Alphabetical List of the Ten Commuter Aircraft Selected for Inclusion in the FAA Commuter Aircraft Fire Study.	4
5. Commuter Aircraft Baggage Areas.	9
6. Commuter Aircraft Stowage Compartments.	21
7. Commuter Aircraft Lavatory Areas.	22
8. Commuter Aircraft Galley Areas.	23
9. Commuter Aircraft Fuselage Area Partitions.	24
10. Commuter Aircraft Cabin Lining Materials.	26
11. Commuter Aircraft Baggage Area Lining Materials.	28
12. Commuter Aircraft Floor Coverings.	29
13. Commuter Aircraft Transparency Materials.	30
14. Commuter Aircraft Seat Materials.	31
15. Commuter Aircraft Fuselage Insulation.	32
16. Commuter Aircraft Wiring Insulation.	33
17. Commuter Aircraft Fire Detection Systems.	45
18. Commuter Aircraft Fire Suppression Systems.	46
19. Commuter Aircraft Hand Fire Extinguishers.	47
20. Commuter Aircraft Oxygen Systems.	49
21. Commuter Aircraft Ventilation Systems.	63

EXECUTIVE SUMMARY

This study describes fire safety systems and airframe design as well as applications of construction materials in cabin areas of ten common commuter class aircraft. The ten commuter aircraft have been selected to represent those aircraft most common in the commuter fleet. The aircraft in this study represent the majority of the current regional airline fleet of aircraft carrying thirty or fewer passenger, and, due to their numbers in service (880 out of 1100 commuter class aircraft), will remain representative of the population for several more years. The trend in the design of commuter airliners, as seen in this study, is that of increasing sophistication in application of materials similar to those found in large commercial aircraft. With the exception of two aircraft, the commuter aircraft are small and offer relatively high performance.

The aircraft in this study illustrate trends in the commuter aircraft industry. The only two piston powered aircraft originated as general aviation aircraft designs some years ago. They are relatively small and simple in both design and materials applications. Of the other and larger eight aircraft, two are at the end of their delivery periods. These are a derivative of aircraft which were adapted to commuter service. One other aircraft, while a relatively new design, is not being delivered currently due to market desire for larger aircraft.

Of the eight larger aircraft, application of modern, composite materials is a major characteristic of the aircraft. Four of the newer and larger designs feature large, rear located, separate baggage compartments, leaving the cabin for seating. Only in two are overhead storage bins found.

Of the ten aircraft, one has a large interior that allows standing headroom in its large interior volume. The other aircraft are much more compact, with interior storage limited to bins at the entry end of the aircraft. Weight saving seems to be key to design success, possibly affecting the selection of various new thermoplastics and composite materials for the interiors. Each aircraft was originally delivered with polyurethane cushions; currently operators and manufacturers are involved in covering these cushions with fire blocking materials to upgrade fire safety.

The two piston powered aircraft use gasoline fired heaters to provide cabin heat and ram air flow to provide outside air for cabin and cockpit cooling; these heaters are not equipped with fire detection or extinguishing systems. The remainder of the aircraft are turbine powered, turboprop aircraft that use engine bleed air for heating and cooling of the interior air. Six of the ten aircraft are unpressurized aircraft while four are of pressurized design. The unpressurized aircraft have oxygen available for the pilots and passengers, often in portable storage form. The pressurized aircraft feature cabin oxygen for the passengers. Each of these aircraft reflect their operating environment of short, low altitude flight legs, not requiring design of oxygen systems characteristic of large commercial aircraft. In some of the aircraft, the fixed oxygen system is an option picked only by operators faced with the need for sustained high altitude operations, such as in mountainous areas. In these aircraft, oxygen is meant for emergency use of the crew and individual passengers with a temporary need.

INTRODUCTION

PURPOSE.

The purpose of this study was to achieve an understanding of the basic fire safety related design and materials application characteristics of aircraft commonly found in the U.S. commuter aircraft fleet. The goals of the study were to:

- Survey the makeup of the commuter fleet to identify ten aircraft that are both common and typical of the commuter aircraft in use.
- For those ten aircraft, identify the materials used in the cabins of the aircraft.
- For those ten aircraft, identify and describe the compartmentation and materials used in partitioning the aircraft.
- For those ten aircraft, identify and describe fire detection and suppression, oxygen, ventilation systems and hand held fire extinguishers.

BACKGROUND.

Since enactment of the Airline Deregulation Act of 1978 there have been major changes in the character of U.S. commercial aviation. Scheduled air carriers have concentrated their resources to meet new competition by forming "hub and spoke" route systems. With major airlines concentrating on larger cities, small towns and cities suffered a loss of air service. In an attempt to meet this need, both existing and new commuter airlines entered the vacated markets and expanded service to other communities not previously served.

In this way a formerly small and ill defined part of the air transportation system changed into a major aviation activity --- commuter or regional airlines. Starting with small aircraft that were originally general aviation in origin and with older aircraft at the low end of the transport aircraft spectrum, the commuter carriers struggled through several years of economic hardship to establish visibility and credibility in the eyes of the traveling public. One of the problems faced by commuter carriers was the lack of modern, economic aircraft to meet the rapidly expanding service needs. Then, in the early 1980s, aircraft and engine manufacturers began to market new aircraft that were modern in design, powered by turboprop engines and carrying up to thirty passengers. Those aircraft, many manufactured overseas, are now becoming a common sight at U.S. airports. The newly created U.S. commuter fleet is now in service and, due to its rapid growth focused in the 1980s, will retain its basic characteristics for many years to come.

Federal Aviation Administration (FAA) aircraft fire safety programs have been primarily devoted to transport category aircraft. A large body of knowledge and experience had been amassed on these aircraft. Today, with the new commuter aircraft in service, no comparable body of information exists for those new commuter aircraft. For this reason, the FAA's Technical Center's (FAATC) Fire Safety Branch initiated this study to document the fire safety design characteristics of the commuter fleet to establish what sort of

research might be necessary in the future and how much of the existing data on aircraft construction and materials carries over to the new commuter aircraft fleet. Since these aircraft have only come into use in the last few years, there is no body of accident experience that is pertinent. Instead the opportunity existed to review the new fleet's characteristics and establish an information base to which future experience could be compared.

THE POPULATION OF COMMUTER AIRCRAFT

PURPOSE.

The first objective of the current Fire Safety Design Aspects of Commuter Aircraft was to develop a list of aircraft for which fire safety design details would be determined. For this stage of the project, commuter class aircraft with passenger capacity of thirty or fewer passengers were reviewed and ten were selected for further study.

APPROACH.

Two separate approaches were used to obtain the final list of commuter aircraft. The first approach was to identify the ten most populous commuter aircraft used in the U.S. while the second approach was to identify the six commuter aircraft being sold or delivered at the highest rates during the most recent two years. From these two lists, a combined list balancing past production against future deliveries was developed.

POPULATION RESEARCH.

According to the FAA's Census of U.S. Civil Aircraft for 1984, the ten most common commuter aircraft were the following:

TABLE 1. THE TEN MOST COMMON COMMUTER AIRCRAFT BASED
ON FAA CENSUS OF CIVIL AIRCRAFT - 1984.

Type	Number
Piper Navajo PA-31	107
Cessna 402	99
Fairchild Metro II SA-226	97
deHavilland Twin Otter DHC-6	97
Beech 99	79
Fairchild Metro III SA-227	70
Embraer Bandeirante EMB-110	68
Pilatus Islander BN-2	27
Casa 212	27
Beech 1900	17

A second list of ten was developed from two other sources, the Regional Airline Association's (RAA) 1986 Annual Report of the Regional/Commuter Airline Industry and the FAA's Aircraft Utilization & Propulsion Reliability Report for May and June, 1986. In comparing these two sources, it was noted that the totals for the different aircraft types varied, yet the top ten commuter aircraft were nearly the same in each source. Balancing the varying

totals on the ten most common aircraft in these sources, the following fleet total was developed.

TABLE 2. THE TEN MOST COMMON COMMUTER AIRCRAFT BASED ON REGIONAL AIRLINE ASSOCIATION AND FAA DATA - 1986.

Type	Number
Cessna 402	190
Piper Navajo PA-31	109
Beech 99	106
deHavilland Twin Otter DHC-6	106
Fairchild Metro II SA-226	103
Fairchild Metro III SA-227	97
Embraer Bandeirante EMB-110	86
British Aerospace BAe Jetstream 3100	83
Beech 1900	47
Shorts 330 SD 3-30	41

The World Aviation Directory tabulation of "Business/Personal Aircraft Unit Shipments" for calendar years 1984, 1985 and for the period January-October, 1986 was used to identify the commuter aircraft being sold or delivered at the highest rate during the most recent two years.

TABLE 3. WORLD AVIATION DIRECTORY TOTALS OF COMMUTER AIRCRAFT DELIVERIES FOR 1984, 1985 AND JANUARY-OCTOBER 1986.

Type	1984 Total	1985 Total	1986 Total
BAe Jetstream 3100	22	34	36
Beech 1900	29	21	13
Cessna 402	11	14	1
deHavilland DHC-6	14	18	2
Embraer EMB-110	9	8	5
Embraer EMB-120	-	6	10
Fairchild SA-227	23	20	23
Pilatus BN-2	5	2	6

Eight, rather than the required six aircraft, were reported since these eight were the only commuter aircraft being delivered in significant numbers in the 1985-1986 period.

POPULATION DEFINITION.

The lists shown in tables 2 and 3 were provided for consideration and compilation into a composite list reflecting both existing commuter aircraft and those likely to be most common in the future due to delivery trends. Such a list was determined after consultation with FAA Central Region representatives responsible for commuter aircraft certification. The final list of ten aircraft for further study was selected from the candidate aircraft and is as follows:

TABLE 4. ALPHABETICAL LIST OF THE TEN COMMUTER AIRCRAFT
SELECTED FOR INCLUSION IN THE FAA COMMUTER AIRCRAFT FIRE STUDY.

British Aerospace BAe Jetstream 3100
Beech 99 (BE-99)
Beech 1900 (BE-1900)
Cessna 402 (CE-402)
deHavilland Twin Otter (DHC-6)
Embraer Bandeirante (EMB-110)
Embraer Brasilia (EMB-120)
Fairchild Metro III (SA-227)
Piper Navajo (PA-31)
Shorts 330 (SD 3-30)


These ten aircraft, in the summer of 1986 represented an approximate total of 880 of the nearly 1100 commuter aircraft counted by the FAA as being in the U.S. commuter aircraft fleet. From this it can be seen that the ten aircraft are representative of the present fleet and likely will remain so for some time to come.



BAe JETSTREAM 3100
19 PASSENGERS



BEECH 99
15 PASSENGERS



BEECH 1900
15 PASSENGERS



CESSNA 402
8 PASSENGERS




TWIN OTTER SERIES 300
20 PASSENGERS




EMBRAER BANDEIRANTE
19 PASSENGERS

FIGURE 1. ILLUSTRATIONS OF THE TEN SELECTED COMMUTER AIRCRAFT (1 of 2 pages)




EMBRAER BRASILIA
30 PASSENGERS



FAIRCHILD METRO III
19 PASSENGERS



PIPER NAVAJO
9 PASSENGERS



SHORTS 330
30 PASSENGERS

FIGURE 1. ILLUSTRATIONS OF THE TEN SELECTED COMMUTER AIRCRAFT (2 OF 2 PAGES)

COMMUTER AIRCRAFT MATERIALS AND SYSTEMS RESEARCH

PURPOSE.

The intent of the Current Fire Safety Design Aspects of Commuter Aircraft was to document the fire safety provisions and design elements of the ten selected aircraft. This documentation focused on three general areas of aircraft design and construction: cabin materials, aircraft compartmentation and fire related systems. For cabin materials, the study covered: cabin and baggage area liners, floor coverings, major transparencies, seats, insulation, cabin area fuselage skin thickness, and flight deck and cabin area wire insulation. For aircraft compartmentation the intent was to portray baggage area location and accessibility, lavatory location and materials of construction, galley location and materials of construction, cabin firewalls and materials of construction, flight deck firewalls and materials of construction, partitions and their composition, and stowage compartments and their composition. For fire related systems this study describes fire detection and suppression systems, on-board hand held fire extinguishers, oxygen systems, and ventilation systems. Both text and illustrations are used in explaining these systems' details.

METHODOLOGY.

For each aircraft a two-fold approach was taken in obtaining the necessary information. Each manufacturer was contacted regarding the information requirements. At the same time, operators of the ten selected aircraft were contacted to obtain similar information. Based upon conversations with manufacturers and operators, representative aircraft configurations were selected. This was due to the variety of configuration options that were available in several of the aircraft. The configuration selected for the study was felt to be the most likely to be encountered or the most common in the fleet, for that aircraft. As an example, though most of the aircraft could be equipped with a galley, galleys were not generally an option selected by operators faced with the need to maximize revenue producing load over often short flight distances and times.

ORGANIZATION.

The data developed in this investigation are organized on a topic basis rather than a model basis. Much of the information is presented through illustrations. Aircraft compartmentation is described in illustrated format in figures 2 through 11. Amplification of some details of compartmentation is offered by text descriptions.

Materials applications, except for fuselage skin thickness, are described in text form with each aircraft being summarized under separate material application, e.g., cabin and baggage area liners are described for each of the ten aircraft, followed by descriptions of floor coverings for each of the ten aircraft. Cabin area fuselage thickness for each of the ten aircraft is described in pictorial form in figures 12 through 21.

Aircraft fire related systems are described using both illustrations and text. Figures 22 through 43 illustrate layout of fire detection and suppression systems, oxygen systems and ventilation systems. This information is supplemented by text descriptions of design specifications and other details.

COMPARTMENTATION

BAGGAGE AREAS.

For purposes of describing the fireworthiness capabilities of cargo or baggage compartments, transport category aircraft cargo/baggage compartments are described by five classes of fireworthiness. Each is typified by differing characteristics of accessibility, ventilation, fire or smoke detection, fire extinguishing, and volume. These classifications are listed in Federal Aviation Regulations Part 25.857 - Cargo Compartment Classification. Though several of the aircraft surveyed for this report were not designed according to the standards of Part 25, which applies to transport category aircraft rather than commuter aircraft, several of the manufacturers have described the fire worthiness characteristics of their aircraft's baggage compartments in terms of the Part 25 classification. The five classes of baggage compartment are summarized, below:

Class A - A compartment in which the presence of fire would be easily discovered while a crewmember is at his or her station and the compartment is easily accessible, in flight.

Class B - A compartment in which there is sufficient access, in flight, to enable a crewmember to effectively reach the entire contents of the compartment with a hand fire extinguisher. Further, when the crewmember is accessing the compartment, no hazardous quantity of smoke, flames, or fire extinguishing agent will enter any compartment occupied by crew or passengers. For this Class of compartment there must be a separate, approved smoke or fire detector at the pilot's or flight engineer's station.

Class C - A compartment not meeting the requirements of either Class A or B, but which has a separate, approved fire or smoke detector at the pilot's or flight engineer's station. Class C compartments will have an approved, built in fire extinguishing system controlled at the pilot's or flight engineer's station. Like the Class B compartment, the Class C compartment must have means to prevent hazardous quantities of smoke, flames, or fire extinguishing agent from entering any compartment occupied by crew or passengers. In addition to these requirements, the Class C compartment will have means to control ventilation and drafts within the compartment so that the fire extinguishing agent can control any fire that may start within the compartment.

Class D - These are compartments in which a fire occurring in the compartment will be completely confined without endangering the safety of the airplane or the occupants. For Class D compartments there will be means of preventing hazardous quantities of smoke, flames, or fire extinguishing agent from entering any compartment occupied by crew or passengers, and both ventilation and drafts will be controlled

so any fire within the compartment will not progress beyond same limits. For Class D compartments consideration will be given to the effect of heat within the compartment on adjacent critical parts of the airplane. For compartments of 500 cubic feet or less volume, an airflow of 1500 cubic feet per hour is acceptable. The volume of a Class D compartment will not exceed 1,000 cubic feet.

Class E - These compartments are used only for the carriage of cargo and must have a separate, approved smoke or fire detection system at the pilot's or flight engineer's station. For these compartments there will be means to shut off ventilation airflow to or within the compartment, and the controls for these means will be accessible to the flight crew in the crew compartment. There will be means to prevent hazardous quantities of smoke, flames, or fire extinguishing agent from entering the flight crew compartment; and required crew emergency exits will be accessible under any cargo loading condition.

Of the ten aircraft, eight used the fuselage area for baggage storage, usually in baggage compartments behind the cabin, and often in smaller compartments forward of the cockpit. In the Cessna 402, Jetstream 3100, Fairchild Metro III, Beech 99, and Piper Navajo, the fuselage baggage area is at the rear of the passenger cabin and is open to the cabin area. Only the Beech 99 series of aircraft featured use of an external belly pod for additional baggage. In the two smallest aircraft, the Cessna 402 and the Piper Navajo, baggage stowage is also possible in enclosed lockers at the top, rear of each of the engine nacelles. This nacelle location is a reflection of the origin of those two aircraft as general aviation aircraft. Figures 2 through 11 illustrate the location of the baggage areas as part of aircraft compartmentation.

TABLE 5. COMMUTER AIRCRAFT BAGGAGE AREAS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Open bin storage at the rear end of the cabin area, (96.7 cubic feet) open and accessible from inside the cabin.
Beech 99	Baggage areas forward of the cockpit (43.9 cubic feet) and behind the cabin (17.1 cubic feet), with the nose baggage not accessible in flight. Rear baggage compartment separated from cabin by webbing. Some aircraft equipped with a fiberglass belly pod (59.4 cubic feet) accessible only from outside.
Beech 1900	Baggage areas forward of the cockpit (13 cubic feet) and behind the cabin (154 cubic feet), neither accessible in flight. Additional baggage in a storage bin at the forward right of the cabin (15 cubic feet) opposite the entry door.

Cessna 402	Baggage areas forward of the cockpit (26 cubic feet), in the top rear section of each engine nacelle (8.9 cubic feet each), and behind the cabin (31.7 cubic feet). The nose and the nacelle baggage compartments are not accessible in flight. The rear baggage compartment is an open bin aft of the entry doorway in the rear of the cabin.
deHavilland Twin Otter	Baggage areas forward of the cockpit (38 cubic feet) and behind the cabin (88 cubic feet). The forward area (Class D) is not accessible in flight, while the rear baggage compartment (Class B) can be accessed through a hatch at the top center of the aft bulkhead of the passenger cabin.
Embraer Bandeirante	Single baggage bin (113 cubic feet) at the rear of the cabin, separated from the cabin by a folding vinyl divider.
Embraer Brasilia	Single Class D baggage compartment (226 cubic feet) behind the rear cabin partition and not accessible in flight.
Fairchild Metro III	Baggage areas forward of the cockpit (45 cubic feet) and behind the rear cabin bulkhead (136 cubic feet), neither accessible in flight. Open baggage bin at the right front of the passenger cabin.
Piper Navajo	Baggage areas forward of the cockpit (14 cubic feet) and in the top rear of each engine nacelle (13.25 cubic feet each), neither accessible in flight. Open baggage area at the rear of the cabin accessible in flight (22 cubic feet).
Shorts 330	Baggage areas forward of the cockpit (45 cubic feet) and behind the cabin (170 cubic feet), neither accessible in flight.




FIGURE 2. BAE JETSTREAM 3100 COMPARTMENTATION




FIGURE 3. BEECH 99 AIRLINER COMPARTMENTATION




FIGURE 4. BEECH 1900 AIRLINER COMPARTMENTATION





FIGURE 5. CESSNA 402 COMPARTMENTATION



**FIGURE 6. TWIN OTTER SERIES 300
COMPARTMENTATION**




FIGURE 7. EMBRAER BANDEIRANTE COMPARTMENTATION




FIGURE 8. EMBRAER BRASILIA COMPARTMENTATION




FIGURE 9. FAIRCHILD METRO III COMPARTMENTATION




FIGURE 10. PIPER NAVAJO COMPARTMENTATION




FIGURE 11. SHORTS 3-30 COMPARTMENTATION

STOWAGE COMPARTMENTS.

Due to the size of most of the ten aircraft, stowage compartments are not common. In the larger aircraft, the Brasilia and Shorts 330, overhead bins are found in the cabin. In the Jetstream 3100 and the Fairchild Metro III, there are bin areas at one end of the cabin near the entry doorway.

TABLE 6. COMMUTER AIRCRAFT STOWAGE COMPARTMENTS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Stowage compartments at the right rear of the cabin opposite the entry doorway.
Beech 99	None.
Beech 1900	None.
Cessna 402	None.
deHavilland Twin Otter	None.
Embraer Bandeirante	None.
Embraer Brasilia	Overhead bins in the cabin only along the right side of the cabin, above the double row of seats. Total volume of 32.1 cubic feet.
Fairchild Metro III	Baggage area/closet at the right forward end of the cabin opposite the doorway.
Piper Navajo	None.
Shorts 330	Overhead storage bins on each side of the cabin above the seats.

LAVATORIES.

Only in the two larger aircraft, the Brasilia and the Shorts 330, are lavatories to be found. The other eight aircraft cabins are configured only for passenger and crew seating.

TABLE 7. COMMUTER AIRCRAFT LAVATORY AREAS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	None.
Beech 99	None.
Beech 1900	None.
Cessna 402	None.
deHavilland Twin Otter	None.
Embraer Bandeirante	None.
Embraer Brasilia	Optionally available and installed in either the right forward or right rear part of the cabin area. Constructed of composite material lined with vinyl. Lavatory over a stainless steel pan, in turn, mounted to the honeycomb cabin floor structure.
Fairchild Metro III	None.
Piper Navajo	None.
Shorts 330	Located in the rear of the cabin area. Compartment panels of vacuum oven cure honeycomb sandwich panel 1/4 inch thick with 1/8 inch cell 1.5 lb./cubic foot Nomex* honeycomb. Facings a single 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.006 inch vinyl faced with 0.001 inch polyvinyl fluoride (PVF) (Schneller Aerfilm). Mouldings and trim pieces are vacuum oven cured multi laminate of phenolic resin pre-impregnated glass cloth (various thicknesses 0.02-0.06 inches). Visible surfaces painted with water base aircraft interior quality emulsion paint. Lavatory door a vacuum oven cure honeycomb sandwich panel with a 3/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Facing of two 0.1mm laminates of phenolic resin pre-impregnated glass cloth on each side. Decor of both sides covered with 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm).

GALLEYS.

As for lavatories, in the study group of aircraft, only the two largest aircraft, the Brasilia and Shorts 330, feature a galley area. This galley is typically small and suited for simple cabin service such as beverages.

* Nomex is a registered trademark for DuPont.

TABLE 8. COMMUTER AIRCRAFT GALLEY AREAS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	None.
Beech 99	None.
Beech 1900	None.
Cessna 402	None.
deHavilland Twin Otter	None.
Embraer Bandeirante	None.
Embraer Brasilia	Optionally installed at the left or right rear of the cabin or just aft of the cabin entry doorway on the left side.
Fairchild Metro III	None.
Piper Navajo	None.
Shorts 330	Located at the rear of the cabin. Locker doors are of vacuum oven cure honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Door facings are one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Door decor is 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm). Galley Locker and caps are vacuum oven cured multi-laminate of phenolic resin impregnated glass cloth of various thickness (0.02-0.06 inch). Visible surfaces painted with water base aircraft interior quality emulsion paint. Locker top panels are vacuum oven cure honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Panel facings are one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Panel decor is 0.001 inch PVF film (Tedlar).

FIREWALLS.

Manufacturers of the commuter aircraft surveyed report none of the aircraft have firewalls incorporated in the design of the cabin/fuselage area.

PARTITIONS.

In the ten aircraft, wood core sandwich panels are common, usually faced with aluminum or fiberglass. In the two newer design aircraft, the Brasilia and the Shorts 330, various combinations of thermoplastic are common. In the case of the Brasilia, newer materials were applied to the aircraft to achieve significant weight reductions.

TABLE 9. COMMUTER AIRCRAFT FUSELAGE AREA PARTITIONS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Partition at the forward edge of the main entry door between the cockpit and cabin constructed of honeycomb laminate. Construction of 0.78 inch Fiberlam (0.75 inch Nomex with epoxy skins of 0.015 inches) and of 0.28 inch Fiberlam (0.25 inch Nomex with epoxy skin of 0.015 inches).
Beech 99	No partitions. Sliding curtain separates pilots and the cabin, curtain fabric matching seat material such as vinyl or wool fabric.
Beech 1900	Sliding door partition separates pilots from cabin, and a partition with hinged top half separates the cabin from the rear baggage area. Partitions constructed of 1 inch aluminum honeycomb and veneer.
Cessna 402	Single partition at the rear of the cabin, separating the cabin and the tail cone area. The partition of plywood construction covered with high pressure laminate.
deHavilland Twin Otter	Forward partition between cabin and cockpit of 0.50 inch plywood core with formica (phenolic) facing. Sliding door in partition of 0.50 inch balsa wood core with formica facing. Rear bulkhead between cabin and baggage compartment of 0.020 inch aluminum and 0.032 inch Acrylic/PVC (Kydex) thermoplastic with naugahyde fabric covering and of 0.032 inch Acrylic/PVC (Kydex) thermoplastic.
Embraer Bandeirante	Sandwich panel behind pilots with aluminum facing on cockpit side over plywood and with formica facing on the cabin side. Partitions behind pilots with fabric curtain across the center opening.
Embraer Brasilia	Partitions between cockpit and cabin and between cabin and rear baggage area. Cockpit partition has a door at the center opening. Cockpit partition is nomex honeycomb with fiberglass facing on the cockpit side and vinyl facing on the cabin side. Baggage compartment partition is composite material faced with vinyl on the passenger side and Aramid (Kevlar) cloth and polyester resin (Gilliner) on the baggage side.
Fairchild Metro III	Partition between cabin and rear baggage compartment. Partition of plywood and steel with vinyl facing.
Piper Navajo	No partitions.

Partitions at the forward and rear of the cabin. The forward bulkhead upper panels and the entire rear bulkhead are constructed with vacuum oven cure honeycomb sandwich panel with 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot nomex honeycomb core. Facings are one ply 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm). The forward bulkhead center panel is vacuum oven cure honeycomb sandwich panel with 3/8 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Facings are two 0.1mm laminates of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm). Forward bulkhead mouldings are vacuum oven cured multi-laminate of phenolic resin pre-impregnated glass cloth of various thickness (0.02-0.06 inches). Visible surfaces are painted with water base aircraft interior quality emulsion paint. The two flight compartment sliding doors are vacuum oven cure honeycomb sandwich panel with 3/16 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb core. Facings are one ply 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side. Decor is 0.001 inch PVF (Tedlar).

MATERIALS

Following is a tabular comparison of the various materials reported, by manufacturers or aircraft operators, as used in selected applications.

LINING MATERIALS.

The description of materials represents those used at original manufacture. Refit of the interiors may result in substitution. Original Bandeirantes were fitted with leather due to its low cost, at that time, in Brazil.

TABLE 10. COMMUTER AIRCRAFT CABIN LINING MATERIALS.

<u>Aircraft Type</u>	<u>Material</u>
BAe Jetstream 3100	Lining for ceiling panels, sidewall jointstrips, passenger service unit (PSU) panel, and infill panel consists of two layers of fiberglass epoxy laminate. Ceiling panels, PSU panel and infill panel of 1/8 inch Nomex honeycomb with phenolic resin pre-preg fiberglass skins. Sidewall panels of 1/8 inch Nomex core with epoxy resin pre-preg fiberglass skins. Window reveal of 0.015 inch epoxy resin fiberglass. Decorative trim of headliners, sidewalls and PSU infill panels of PVF (Schneller Aerfilm) and Wardle Storey's Storey trim.
Beech 99	Acrylic/PVC (Kydex) with curtains of 56% rayon and 46% cotton.
Beech 1900	Acrylic/PVC (Kydex) with curtains of 56% rayon and 46% cotton.
Cessna 402	Combinations of leathers, vinyls and carpets. Sidewall upholstery backing panels of thin gauge aluminum (0.020 or less) and window escutcheons of thermoplastic sheet approximately 0.09 thick.
deHavilland Twin Otter	Lower cabin side (dado) panels of 0.025 aluminum covered with Naugahyde vinyl fabric and woven wool/nylon carpet. Sidewalls of 0.025 aluminum covered with Naugahyde vinyl fabric. Naugahyde covered ducts for cold air and 0.060 Acrylic/PVC (Kydex) covered overhead ducting.
Embraer Bandeirante	Liner of leather covered aluminum panels.
Embraer Brasilia	Liner of moulded fiberglass/ Kevlar*/ Nomex/ honeycomb/ carbon fiber with vinyl lining on passenger side.
Fairchild Metro III	Nomex honeycomb.
Piper Navajo	ABS/PVC polymer (Royalite).
Shorts 330	Cabin side and door panels of vacuum oven cure honeycomb sandwich panel with core of 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb; facing of one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side; and decor of 0.006 inch vinyl faced with 0.001 inch PVF (Schneller Aerfilm).

* Kevlar is a DuPont registered trademark.

Ceiling panels of vacuum oven cure honeycomb sandwich panels with a core of 1/4 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb; facings of one 0.1mm laminate of phenolic resin pre-impregnated glass cloth on each side; and decor of water base aircraft interior quality emulsion paint.

Forward exit sign boxes and forward vertical air conditioning duct covers of vacuum oven cured multi-laminate of phenolic resin pre-impregnated glass cloth (various thicknesses 0.02-0.06 inch). Visible surfaces covered with Schneller Aerfilm.

Door surrounds, framings and mouldings, and fairing pieces of vacuum oven cured multi-laminate phenolic resin pre-impregnated glass cloth (various thicknesses 0.02-0.06 inch). Visible surfaces painted with water base aircraft interior quality emulsion paint.

Window reveals and Passenger Service Unit (PSU) panels of vacuum formed polycarbonate (Lexan).

TABLE 11. COMMUTER AIRCRAFT BAGGAGE AREA LINING MATERIALS

Baggage liners are shown as original equipment. Once in service, operators report substitution of aluminum faced liners for improved durability.

<u>Aircraft Type</u>	<u>Material</u>
BAe Jetstream 3100	Three layers of fiberglass with epoxy resin. Lining of Schneller Aeramat (fiberglass backed vinyl). Cabin stowage compartments of honeycomb and laminate. PVF decorative trim of Schneller Aerlam and Aerfilm, Wardle Storey's Storeytrim, Oberflex's Wood Veneer (fire retardant grade) and 100% Nylon woven pile loop fabric (Langenthal Multi Point).
Beech 99	Fuselage baggage area Aluminum sheet T2024 Alclad, 0.040 thickness. Belly pod of fiberglass with no liner.
Beech 1900	Aramid (Kevlar) cloth and polyester resin (Gilliner).
Cessna 402	Standard Alclad aluminum skin substructure lined with carpeting. Some stiffening done with aluminum honeycomb and fiberglass reinforcement.
deHavilland Twin Otter	Nose baggage area liner of 3/8 inch Balsawood core with fiberglass facing. Tail baggage area liner of 3/8 inch Balsawood core with aluminum liner.
Embraer Bandeirante	Aramid (Kevlar) cloth and polyester resin (Gilliner).
Embraer Brasilia	Aramid (Kevlar) cloth and polyester resin (Gilliner). Cabin overhead bins lined with vinyl. Floor of fiberglass with high density Nomex core, protected with corrugated aluminum sheets.
Fairchild Metro III	Vinyl covered sheet aluminum.
Piper Navajo	ABS/PVC polymer (Royalite).
Shorts 330	Front baggage compartment front, sides, and ceiling of vacuum oven cure honeycomb sandwich panel with a core of 3/16 inch thick, 1/8 inch cell, 1.5 lb./cubic foot Nomex honeycomb. Rear bulkhead of front baggage compartment of light alloy honeycomb sandwich panel with a core of 1.18 inch thick, 3/16 inch cell 5056 alloy 24G L72 aluminum skin on each side.

Aft baggage compartment panels of vacuum oven cure honeycomb sandwich panel with a core of 3/16 inch thick, 1/8 inch cell, 1.5 lb./cubic foot nomex honeycomb; an inner facing of two 0.1mm laminates of phenolic resin pre-impregnated glass cloth; and a decor of 0.001 inch PVF (Tedlar).

FLOOR COVERINGS.

With few exceptions, wool carpeting is the material used as floor covering in the ten selected aircraft.

TABLE 12. COMMUTER AIRCRAFT FLOOR COVERINGS.

<u>Aircraft Type</u>	<u>Material</u>
Bae Jetstream 3100	Side floor panels of 0.28 inch fiberlaminat (Nomex core with epoxy skins). Center aisle panels of 0.405 inch fiberlam. Main cabin carpeting is 100% wool face yarn with 100% synthetic backing (Langenthal Melair).
Beech 99	100 % wool carpeting.
Beech 1900	100 % wool carpeting.
Cessna 402	100% wool or rubber mats.
deHavilland Twin Otter	Woven wool/nylon carpeting.
Embraer Bandeirante	Fabric carpet of operators' choice.
Embraer Brasilia	Fabric carpet over carbon fiber/ nomex sandwich floor on mid-1987 and earlier aircraft. Aircraft from late 1987 changed floor to balsa wood core with fiberglass facing on each side.
Fairchild Metro III	Wool carpet.
Piper Navajo	20 inch Tiffany - tufted wool carpet with latex backing (General Motors Spec W2RB).
Shorts 330	Cabin seating area has 100 % wool, woven carpet with cut pile treated with fire retardant. Entrance/lavatory and cockpit areas have fiberglass backed vinyl floor covering (Schneller Aermat).

MAJOR TRANSPARENCIES.

Acrylic polymer, commonly called Plexiglas, is the usual material for windows in the ten aircraft. The larger aircraft feature a layer, or lam, of glass on the outer face of the cockpit windscreens or windshields. Side windows are of acrylic polymer.

TABLE 13. COMMUTER AIRCRAFT TRANSPARENCY MATERIALS

<u>Aircraft Type</u>	<u>Material</u>
BAe Jetstream 3100	Inner and outer cabin transparencies of Perspex DTD 5592 acrylic polymer sheet.
Beech 99	Single pane cabin window of 0.050 inch acrylic polymer (Plexiglas).
Beech 1900	Single laminated pane of acrylic polymer.
Cessna 402	Standard window is laminate cast acrylic polymer.
deHavilland Twin Otter	Two layer cabin windows with an inner panel of acrylic polymer and an outer panel of acrylic/PVC alloy. Outer panel thickness is 0.08 inches. Cockpit side windows of 0.25 inch Plexiglas and front windscreens acrylic polymer laminate faced with glass.
Embraer Bandeirante	Cabin windows of single pane acrylic polymer with inner scratch shield of acrylic polymer. Cockpit windshield is glass/acrylic laminate if heated.
Embraer Brasilia	Cabin and cockpit side windows of single pane, stretched acrylic polymer with inner scratch shield of acrylic polymer. Cockpit windshield is glass faced laminated polycarbonate.
Fairchild Metro III	Acrylic polymer cabin windows.
Piper Navajo	Acrylic polymer cabin windows.
Shorts 330	Flat acrylic polymer sheet (Perspex) cabin windows. Moulded Perspex cockpit windows. Laminated acrylic faced with glass (Perplex). Earlier aircraft windshields not faced with glass.

CABIN SEAT MATERIALS.

Seating universally uses urethane foam, though heat resistant wrappings are soon to be applied. These wrappings are not yet in use. Older design aircraft retain use of steel frame seating.

TABLE 14. COMMUTER AIRCRAFT SEAT MATERIALS

<u>Aircraft Type</u>	<u>Material</u>
BAe Jetstream 3100	Seat legs are formed sheet aluminum. Seat bottom is honeycomb aluminum panel with epoxy skins. Seat back is graphite epoxy resin as is the seat arm. Seat back cushion is open cell polyurethane foam and bottom cushion is open cell polyurethane foam combined with closed cell polyethylene foam (Ethafoam) providing flotation capability. A fire blocking layer of PBI/Kevlar/Nomex scrim felt is used on the cushions. Upholstery is usually 90% wool/ 10% nylon. 100% wool is used in some aircraft.
Beech 99	Steel frame with urethane foam cushioning. 100 % wool fabric with Zyrpro flame retardant treated covers with vinyl trim.
Beech 1900	100% wool fabric cover with Zyrpro flame retardant and vinyl trim.
Cessna 402	Pilots' seats are steel framed. Passenger seat frames are a composite material of Kevlar laminate (Enviroform). Cushioning is polyurethane foam and seat covering is 100% wool with vinyl trim.
deHavilland Twin Otter	Metal framed, urethane foam cushioned seats with naugahyde vinyl trim and upholstery. Kydex thermoplastic back panel of 0.040 inches thickness.
Embraer Bandeirante	Aluminum framed, urethane cushioned, leather covered seats. On later aircraft, seat covering material is optional.
Embraer Brasilia	Aluminum/carbon fiber/Kevlar seat frame with urethane cushion and fabric covering.
Fairchild Metro III	Steel and aluminum framed fiberglass bucket seats.
Piper Navajo	100 % wool fabric with vinyl trim.
Shorts 330	Tubular steel frame with foam cushions on nylon support diaphragms. 100 % wool covers.

INSULATION MATERIALS.

Fiberglass cabin insulation is nearly universal in application.

TABLE 15. COMMUTER AIRCRAFT FUSELAGE INSULATION

<u>Aircraft Type</u>	<u>Material</u>
BAe Jetstream 3100	Cabin insulation is fiberglass Microlite PF 105W (0.6 pound per cubic foot) bagged in Orcofilm AN 18L.
Beech 99	Fiberglass.
Beech 1900	Fiberglass.
Cessna 402	Fiberglass.
deHavilland Twin Otter	Cabin not insulated.
Embraer Bandeirante	Fiberglass insulation with single coated vinyl foam tape (Scotchfoam) applied in high vibration areas such as next to the propellers. Earlier aircraft used rockwool rather than fiberglass.
Embraer Brasilia	Fiberglass insulation with single coated vinyl foam tape (Scotchfoam) applied in high vibration areas such as next to the propellers.
Fairchild Metro III	PVC/Nitrile foam (Ensolute) and fiberglass batting.
Piper Navajo	Fiberglass and Flexweave 1000 Cloth (fiberglass/vitreous aluminosilicate fibers with organic binders).
Shorts 330	Sound and thermal insulation of water repellant fiberglass with phenolic resin binder 0.61 lb./cubic foot. Covering of neoprene coated nylon cloth or nylon reinforced PVF film (on later aircraft).

WIRE INSULATION MATERIALS.

Wiring conforms to various military specifications. Only in the Shorts 330 is use of Kapton insulated wiring reported.

TABLE 16. COMMUTER AIRCRAFT WIRING INSULATION

<u>Aircraft Type</u>	<u>Material</u>
Bae Jetstream 3100	Cabin and flight deck wiring as follows: Type 1 (Raychem Specification 44) - Specification Standard - wires: MIL-W-81044; cables MIL-C-27500 and MIL-C-7078. Type 2 (PTFE) Equipment wire - Specification Standard BSG 210, ISO 2032 and DEF STAN 61-12 Part 8 or MIL-W-16878. Type 5 (Aluminum cable) - Specification Standard - BNAE: L52-120, L52-125. Type 1 is the majority of the wiring. Type 2 used in some internal panel wiring. Type 5 is used for starter/generator feeders in wing and cabin areas.
Beech 99	Cabin and flight deck wiring routing, type and clamping in accordance with MIL-W-5088A. Non-shielded stranded wire of MIL-W-5086B or MIL-W-81044/9. Shielded stranded wire of MIL-C-7078B Class 4 or MIL-C-27500. Teflon insulated or high temperature stranded wire of MIL-W-22759/7, MIL-W-22759/8, MIL-W-25038, MILSPEC 17411, or MIL-W-16878D Type E. MIL-W-16878D Type E wire is not to be used in any harness which is supported by the structure or any application where it is exposed to abrasion.
Beech 1900	Cabin and flight deck wiring routing, type and clamping in accordance with MIL-W-5088A. Non-shielded stranded wire of MIL-W-5086B or MIL-W-81044/9. Shielded stranded wire of MIL-C-7078B Class 4 or MIL-C-27500. Teflon insulated or high temperature stranded wire of MIL-W-22759/7, MIL-W-22759/8, MIL-W-25038, MILSPEC 17411, or MIL-W-16878D Type E. MIL-W-16878D Type E wire is not to be used in any harness which is supported by the structure or any application where it is exposed to abrasion. All wiring of MIL-W-22759 and shielded wiring of MIL-C-27500.
Cessna 402	Cabin and flight deck wiring of MIL-W-81044/9 (Polyalkene-inner and polyvinylidene fluoride-outer). MIL-W-5086B/2 (Polyvinyl chloride-inner and PVC-glass-nylon jacket). MIL-W-81044/12 (Polyalkene-inner and polyvinylidene fluoride-outer). MIL-W-22759/8 (Polytetrafluoroethylene). MIL-W-5086A/1 (Polyvinylchloride-inner and extruded clear nylon jacket). MIL-W-22759/2 (Polytetrafluoroethylene). MIL-W-16878E/4 (Per Specification depending on "/X" number). Polytetrafluoroethylene (TFE) when specified conforms to L-P-403, Type III (ASTM-D-1457-83).

deHavilland Twin Otter	Cabin and flight deck wiring of MIL-W-5086 and MIL-W-22759/13.
Embraer Bandeirante	Cockpit avionics wiring is Tefzel extruded insulation of MIL-W-22759/35 24 gauge wire. Airframe wiring is MIL-W-5086/1 and /2 wiring with polyvinylchloride (PVC) insulation. High temperature wiring used in engine nacelles is MIL-W-22759/6 Polytetrafluoroethylene (TFE) insulated. Fire resistant nacelle wiring is MIL-W-25038 TFE insulated.
Embraer Brasilia	All wiring MIL-W-22759(TFE).
Fairchild Metro III	Ethylenetetrafluoroethylene (ETFE).
Piper Navajo	Cabin wiring since, 1980 MIL-W-81044/9; prior to 1980 MIL-W-5086/7. Flight deck wiring MIL-W-25038B.
Shorts 330	Cabin and flight deck wiring of three layers: PVC inner, glass braid center and nylon outer. On later aircraft, size 22 wire has polyimide (Kapton) insulation.

FUSELAGE SKIN THICKNESS.

Fuselage skin thickness of the cabin areas of the ten commuter aircraft is illustrated in figures 12 through 21. Thicknesses shown in the illustrations are measured in inches, e.g., .040 or .025 equal 0.04 inches and 0.025 inches.




FIGURE 12. BAE JETSTREAM 3100 FUSELAGE SKIN THICKNESS




FIGURE 14. BEECH 1900 AIRLINER FUSELAGE SKIN THICKNESS




FIGURE 15. CESSNA 402 FUSELAGE SKIN THICKNESS




FIGURE 16. TWIN OTTER SERIES 300
FUSELAGE SKIN THICKNESS




FIGURE 17. EMBRAER BANDEIRANTE FUSELAGE SKIN THICKNESS




FIGURE 18. EMBRAER BRASILIA FUSELAGE SKIN THICKNESS





FIGURE 19. FAIRCHILD METRO III SKIN THICKNESS



*NOTE: MATERIAL IS ALL 2024-T3 ALUMINUM EXCEPT WHERE NOTED BY *, WHICH IS 2024-T4 ALUMINUM (HEAT TREATED AFTER FORMING)

FIGURE 20. PIPER NAVAJO FUSELAGE SKIN THICKNESS

SYSTEMS

FIRE DETECTION.

Types of fire detection systems vary, but new and larger aircraft feature continuous loop sensors featuring heat sensing through a pressurized gas. Embraer and Shorts aircraft feature baggage compartment smoke detectors; Beech offers these as an option on the Beech 1900.

TABLE 17. COMMUTER AIRCRAFT FIRE DETECTION SYSTEMS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Fault Free Fire Detection (FFF) type system of Graviner HTL-heat sensing fire wire detecting changes in wire capacitance. System located in each engine nacelle.
Beech 99	Three photo-conductive cells sensitive to infrared rays are located in each nacelle and in the cabin center aisle floor aft of the main wing spar. Optional smoke detectors were available for the nose avionics compartment and adjacent to fuselage fire detectors.
Beech 1900	Temperature sensitive fire-loop located in each nacelle.
Cessna 402	Three heat sensitive detectors located in each engine nacelle.
deHavilland Twin Otter	Four thermal switches located in each engine nacelle.
Embraer Bandeirante	Two photocell smoke detectors in the cabin area and one in the baggage area. Older aircraft with three bimetallic heat sensors in the engine nacelles; newer aircraft have closed loop, pressurized gas heat sensing loops in the nacelle.
Embraer Brasilia	Cabin/baggage compartment smoke detectors in a labyrinth assembly containing a constant light source, a photocell, a test light and associated circuitry; two located in the cabin ceiling, one in the baggage compartment ceiling and one under the baggage compartment flooring. Engine nacelles have three heat sensors - one in the accessory section, one in the exhaust area and one in the landing gear wheelwell. Another heat sensor is located on the auxiliary power unit in the tail.

Fairchild Metro III	Bi-metal heat sensors in the engine compartments.
Piper Navajo	Piper Navajo Chieftain (piston powered) has no installed detection system. Turbine powered Navajo PA-31-1040 has three 450 degree fahrenheit thermal sensors in each engine compartment.
Shorts 330	Cabin smoke detectors: 2 in the forward cabin area, two in the aft cabin area and one in the baggage compartment. Both engine nacelles equipped with heat sensitive continuous-loop wire detectors.

FIRE SUPPRESSION.

Fire suppression for engines and auxiliary power units (APU) uses Halon 1301, except in the Shorts 330.

TABLE 18. COMMUTER AIRCRAFT FIRE SUPPRESSION SYSTEMS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Two fire bottles in each main wheelwell. Each bottle contains 4.5 pounds CBrF3 (Bromotrifluoromethane) / Halon 1301 charged by dry nitrogen. No discharge duration specified.
Beech 99	One cylinder containing 2 pounds of Halon located in each engine nacelle. Nozzled into the engine compartment with approximate discharge duration of 5 seconds.
Beech 1900	Two cylinders in each engine nacelle each containing 2 pounds of Halon and each with a discharge duration of approximately five seconds. Cylinders are discharged one at a time allowing up to four "shots" for one engine.
Cessna 402	One bottle in each nacelle containing 2.1 pounds Halon 1301 (Bromotrifluoromethane) with a discharge duration of no more than 2 seconds.
deHavilland Twin Otter	American Standard system of one bottle in each nacelle of 1.37 pounds Halon 1301 (CBrF3 - Bromotrifluoromethane) charged to 450 psi at 70 degrees Fahrenheit. Discharge duration not specified.

Embraer Bandeirante	Aircraft complying with SFAR 41 have one 2.5 lb. bottle of Halon 1301 in each wheelwell useable in each engine. Bottle provides a single charge of Halon to the engine accessory section.
Embraer Brasilia	6.5 pounds of Halon 1301 agent (CBrF3 Bromotrifluoromethane) per engine nacelle for the engine and wheelwell, and one one pound bottle of Halon 1301 at the tail mounted APU. No discharge duration specified.
Fairchild Metro III	One Halon 1301 (Bromotrifluoromethane) bottle with an agent amount of 3.5 pounds and a discharge duration of five seconds.
Piper Navajo	Navajo Chieftain has no engine fire suppressions system. The Navajo PA-31-1040 has a Halon 1301 system in each nacelle. Approximate discharge duration of four seconds.
Shorts 330	Four bottles of Halon 1211, two in each wing aft of the engine nacelle. 2.0 pound charge of agent per bottle. No discharge duration specified.

HAND EXTINGUISHERS.

Halon 1211 fire extinguishers have been installed in each aircraft except the EMB-110 Bandeirante. New Bandeirantes are not currently sold in the U.S. Operators may upgrade, voluntarily, to Halon 1211 extinguishers. In the Shorts 330 the Halon 1211 extinguishers can be directed into baggage areas through special couplings and tubing manifolds.

TABLE 19. COMMUTER AIRCRAFT HAND FIRE EXTINGUISHERS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Two extinguishers, one in the cockpit to the left of the left seat and one in the cabin behind the aft right passenger seat. Nitrogen charged Halon 1211 (BCF) with the cockpit bottle holding 5.4 pounds of agent and the cabin bottle holding 6.3 pounds of agent.
Beech 99	Two extinguishers, one under the right cockpit seat and one behind the aft left or right passenger seat in the cabin. Each bottle is a two pound Halon 1211 bottle.

Beech 1900	Two 2 pound Halon 1211 bottles, one under the right cockpit seat and the other next to the front entry door.
Cessna 402	One 2.5 pound Halon 1211 bottle beneath the right cockpit seat.
deHavilland Twin Otter	Two 2 pound Halon 1211 bottles, one on the cockpit floor between the seats and one on the right half of the passenger cabin door.
Embraer Bandeirante	A 2.2 pound carbon dioxide extinguisher bottle mounted on the pilot's seat back and one dry chemical extinguisher bottle behind the rear passenger seat and mounted on the bulkhead (SFAR 41 aircraft).
Embraer Brasilia	Two 2.5 pound Halon 1211 bottles, one behind the left cockpit seat and the other below the flight attendant seat at the forward entry door.
Fairchild Metro III	Two 2.5 pound Halon 1211 bottles, one behind the left cockpit seat and the other next to the front entry door.
Piper Navajo	One 2.5 pound Halon 1211 bottle under the right cockpit seat.
Shorts 330	Two 2 pound Halon 1211 bottles, one behind the right cockpit seat and one on the emergency hatch above the right rear exit door (by the galley).

OXYGEN SYSTEMS.

For nine of the ten commuter aircraft, use of cylinders of compressed (1850 psi) oxygen is standard. The Embraer Brasilia may be fitted with an optional oxygen system featuring oxygen generators; this installation is not common. Each, except the Shorts 330, either has or can have a fixed oxygen system installed. The Shorts 330 uses only two supplementary oxygen bottles for the pilots and passengers. The Bandeirante and the Twin Otter normally are equipped only with a portable oxygen bottle for each pilot.

TABLE 20. COMMUTER AIRCRAFT OXYGEN SYSTEMS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	EROS 1409 liter (49.8 cubic foot) system. Cylinder storage behind the aft pressure bulkhead with line routing next to the cabin wall behind paneling and insulation. No special protective measures. Monel or stainless steel oxygen lines.
Beech 99	Cylinder storage in the nose. Lines routed overhead in the cabin with the cited protective measure being routing of oxygen lines away from other types of system lines. Lines of stainless steel with some aluminum.
Beech 1900	Twin cylinder storage, in the nose, of 76.5 cubic feet of compressed oxygen. Overhead line routing in the cabin wall away from other lines and behind paneling and insulation. Lines of stainless steel and some aluminum.
Cessna 402	Cylinder storage, in the nose, of 44 cubic feet of compressed oxygen (114.9 cubic foot optional system). Lines routed on the left side and top of cabin. Lines of 5052-0 and 6061-0 aluminum. Cessna design specification requires oxygen system installation not be in close proximity to fuel, oil and hydraulic systems. It is further directed that oxygen systems will not be contaminated by leaking fuel, oil and hydraulic fluids. The oxygen lines, fittings and equipment are required to be at least six inches away from fuel, oil and hydraulic systems. Deflector plates are stipulated where necessary to keep fuel, oil and hydraulic fluids from oxygen system components. Heating system ducts must be routed apart from oxygen system components or insulated to prevent heating of the oxygen system.
deHavilland Twin Otter	Commuter Twin Otters normally were not equipped with oxygen systems.
Embraer Bandeirante	Two portable cylinders (1850 psi and 115 cubic feet) for the pilots.

Embraer Brasilia

Cylinder storage of compressed oxygen (39 cubic feet at 1850 psi) in the flight attendant cabinet at the front of the cabin, supplemented by portable oxygen cylinders behind the right cockpit seat and next to the flight attendant seat. Line routed along the top of the cabin. Standard passenger oxygen system is two portable cylinders with two outlets each (adequate for 10 percent of cabin occupants). The optional system consists of oxygen chemical generators supplying oxygen for all occupants. There is one additional portable cylinder at the flight attendant station for therapeutic use.

Fairchild Metro III

High pressure (2000 psi) oxygen cylinder storage aft of the cargo compartment. From the cylinder to the selector valve the lines are routed along the side of the cabin between the inner liner and the skin. From the selector valve to the users the lines are run overhead in the cabin between the inner liner and the skin. Lines have local chafe guarding and threading compound is in accordance with Mil-T-5542B. Lines are of aluminum, steel, and copper. Passenger distribution lines are of nylon.

Piper Navajo

Cylinder storage of either 22 or 115 cubic feet of compressed oxygen in either the tail or nose. Lines are routed down the top center of the fuselage and are mounted in chafe grommets at passages through bulkheads. Lines are of 5050-0 aluminum.

Shorts 330

No fixed system is installed. Portable oxygen is available and stored in one bottle in the aft cabin storage area on the left side and at the right hand cockpit entrance from the cabin.

Fire suppression, fire detection, and oxygen systems are illustrated in figures 22 through 30. Figure 31 illustrates fire detection and suppression systems. Figure 32 illustrates oxygen system, and figure 33 illustrates fire suppression, fire detection, and oxygen systems.





FIGURE 22. BAE JETSTREAM 3100 FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS



(1) HEATER AND THERMO SWITCH USED ON SOME EARLIER INSTALLATIONS, PRIOR TO U-165

(2) OXYGEN SYSTEM USED ONLY ON U-50, U-165 AND AFTER

(3) THE SMOKE DETECTOR SYSTEM IS NOT OFFERED ON U-50, U-165 AND AFTER

(4) ON U-80 AND AFTER, THE PLUMBING FOR THE RH ENGINE RUNS DOWN THE RIGHT SIDE OF THE NACELLE, SIMILAR TO THE LH ENGINE

FIGURE 23. BEECH 99 AIRLINER FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS




FIGURE 24. BEECH 1900 AIRLINER FIRE DETECTION & SUPPRESSION SYSTEMS





FIGURE 25. BEECH 1900 AIRLINER OXYGEN SYSTEMS




FIGURE 26. CESSNA 402 FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS




FIGURE 27. TWIN OTTER SERIES 300
FIRE DETECTION, FIRE SUPPRESSION,
AND OXYGEN SYSTEMS




FIGURE 28. EMBRAER BANDEIRANTE FIRE DETECTION & SUPPRESSION SYSTEM




FIGURE 29. EMBRAER BRASILIA FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS





FIGURE 30. FAIRCHILD METRO III FIRE DETECTION, FIRE SUPPRESSION, AND OXYGEN SYSTEMS



**FIGURE 31. PIPER NAVAJO 1040 (TURBINE)
FIRE DETECTION AND SUPPRESSION SYSTEMS**




FIGURE 32. PIPER NAVAJO OXYGEN SYSTEM




FIGURE 33. SHORTS 3-30 FIRE DETECTION, FIRE SUPPRESSION AND OXYGEN SYSTEMS

VENTILATION SYSTEMS.

Older and smaller aircraft are unpressurized. Where the aircraft is turbine powered, engine bleed air is used for air conditioning and heating. Reciprocating engined aircraft, (CE-402 and Piper Navajo) use gasoline combustion heaters to warm the cabin air. These heaters are not equipped with fire detection or suppression systems.

TABLE 21. COMMUTER AIRCRAFT VENTILATION SYSTEMS

<u>Aircraft Type</u>	<u>Descriptions</u>
BAe Jetstream 3100	Pressurized aircraft with engine bleed air used for heated and cooled air, or with plain ram airflow of outside air. The air outflow is through a valve at the rear pressure bulkhead. Air charge occurs in 2.17 minutes at 25,000 feet and 1.51 minutes at sea level. Air outflow rate is a Mass Flow Rate of 20 pounds per minute and Volume Flow Rate of 333 cubic feet per minute at 25,000 feet. At sea level the Mass Flow Rate is 36 pounds per minute and Volume Flow Rate is 480 cubic feet per minute. Duct material is of aluminum alloy, G.R.P. and proprietary lightweight ducting. G.R.P. is glass reinforced plastic -- in this case two layers of fiberglass cloth with phenolic resin. Flexible ducting of polyurethane coated nylon fabric supported by PVDF (polyvinyl difluoride) filament. Floor ducting of 0.28 inch fiberlaminat (Nomex core with epoxy fiberglass skins).
Beech 99	Unpressurized aircraft using ram air flow. Time for air change is 30 to 60 seconds depending on ram pressure. The air outflow location is an exhaust at the rear of the fuselage and the outflow rate is not specified. Duct material is fiberglass.
Beech 1900	Pressurized aircraft using either ram airflow or engine bleed air for heated or cooled air. Time for air change is 30 to 60 seconds, depending upon pressure differential with the air outside the cabin. The outflow valves are located in the aft cabin with outflow rate not specified. Duct material is fiberglass.
Cessna 402	Unpressurized aircraft using ram airflow from nose and dorsal fin intakes. Time for air change is variable depending upon adjustment of ventilation controls. Air outflow is through an exhaust at the rear of the cabin. Duct materials are fiberglass, aluminum sheet metal, flexible rubber ducting and some thermoform plastics.

deHavilland Twin Otter	Unpressurized aircraft using ram airflow collected from a scoop beneath the cockpit and distributed through a ducting system. Heat for the ram air is obtained from engine bleed air. Airflow rates are not known. Air exits from an exhaust at the top of the cabin center. Duct materials are 0.060 and 0.080 polycarbonate (Lexan).
Embraer Bandeirante	Unpressurized aircraft using engine bleed air for circulation after heating or cooling. Ram air circulation is obtainable with two NACA air inlets in the dorsal fin providing the air source.
Embraer Brasilia	Cabin and cockpit are supplied by separate air ducting with cross connecting capabilities. Pressurized (7.2 psi) aircraft using ram airflow and engine or APU bleed air for heating and cooling of recirculated air. Composite material ducting reinforced with fiberglass.
Fairchild Metro III	Pressurized aircraft (7.0 psi) using ram air and engine bleed air for heating and cooling of airflow. Bleed air from a single engine yields a time for air change of less than 6 minutes, while using dual engine bleeds yields a change in less than 3 minutes. The outflow valve is located in the aft pressure bulkhead behind the cargo compartment. Air outflow rate is 22 lbs. minimum with the rate dependent on outside air temperature, cabin temperature, cabin altitude, pressure altitude, throttle settings and the number of environmental control unit (ECU) packs operating. Duct material is aluminum and silicone impregnated fiberglass.
Piper Navajo	Unpressurized aircraft using ram airflow. Outflow location is venting at the tail with no rate specified. Ducting is of fiberglass.
Shorts 330	Unpressurized aircraft using ventilation blowers and no ram air. Time for air change is unspecified and outflow is from the rear of the cabin at a rate of 15 to 25 lb. per minute. Duct material is reinforced, insulated plastic.

Figures 34 through 43 illustrate ventilation systems.




FIGURE 34. BAE JETSTREAM 3100 VENTILATION SYSTEM




FIGURE 35. BEECH 99 AIRLINER VENTILATION SYSTEM




FIGURE 36. BEECH 1900 AIRLINER VENTILATION





FIGURE 37. CESSNA 402 VENTILATION



**FIGURE 38. TWIN OTTER SERIES 300
VENTILATION SYSTEM**




FIGURE 39. EMBRAER BANDEIRANTE VENTILATION




FIGURE 40. EMBRAER BRASILIA VENTILATION SYSTEM




FIGURE 41. FAIRCHILD METRO III VENTILATION SYSTEM

1. HEATER INSTALLATION
2. HEAT-FRESH AIR OUTLET
3. DEFROSTER OUTLET
4. LEVER, COCKPIT AIRFLOW
5. LEVER, CABIN AIRFLOW
6. LEVER, DEFROSTER
7. LEVER, TEMPERATURE CONTROL
8. HEAT-FRESH AIR CONTROL BOX
9. FRESH AIR OUTLET, COCKPIT
10. HEAT-FRESH AIR OUTLET
11. CONTROL, FRESH AIR, RIGHT
12. CONTROL, FRESH AIR, LEFT
13. FRESH AIR OUTLET, CABIN
14. SCOOP, FRESH AIR
15. VENT OUTLET, CABIN
16. SCOOP, CABIN EXHAUST




FIGURE 42. PIPER NAVAJO VENTILATION SYSTEM




FIGURE 43. SHORTS 3-30 VENTILATION SYSTEM

SUMMARY

The ten commuter aircraft selected for this study represent not only those aircraft most common in the commuter fleet, but also are representative of those most commonly being delivered to operators. The ten commuter aircraft in this study represent the majority of the current regional airline fleet of aircraft carrying thirty or fewer passengers, and, due to their numbers in service (880 out of 1100 commuter class aircraft), will be representative of the population for several more years.

The aircraft in this study illustrate trends in the commuter aircraft industry. The Cessna 402 and Piper Navajo originated as general aviation aircraft designed some years ago. They are relatively small, piston powered and simple in both design and materials applications. In the case of the Navajo, a turbine engine version has recently been placed on the market as a means of keeping the airframe saleable. The piston powered Navajo is not required to be equipped with engine fire detection and suppression capability while the turbine powered version is.

Of the other and larger eight aircraft, the deHavilland Twin Otter came into service in the late 1960s. It is also a very simple aircraft with, as an example, no cabin insulation. It is larger than newer aircraft of similar capacity, a characteristic derived from its development as an aircraft able to serve as the means of transportation and supply for remote, undeveloped areas. Both the Twin Otter and its contemporary, the Beech 99, are at the end of their delivery periods. Each is a derivative of older aircraft which were adapted to commuter service. Relatively new thermoplastics have been applied in each of these two aircraft, on a limited basis. The Embraer Bandeirante, though of new design, is not being delivered currently due to cost and market desire for larger aircraft.

In the other six aircraft, application of more modern materials is a major characteristic of the designs of the aircraft. The Fairchild Metro III makes some use of plywood as a core material to certain dividers, however, the predominant trend is to newer materials. The Shorts 330 is a large aircraft that features an interior purposefully appearing like that of airline aircraft operated by Part 121 commercial carriers. The Shorts 330, the Embraer Brasilia, the Metro III and the Beech 1900 each feature large, rear located, separate baggage compartments, leaving the cabin for seating. Only in the Shorts 330 and the Brasilia are there overhead storage bins installed.

Of the ten aircraft, only the Shorts 330 has a large interior that allows standing headroom in its large interior volume. The other aircraft, are much more compact, with interior storage limited to bins at the entry end of the aircraft.

Weight saving and durability seem to be keys to design success, possibly affecting the selection of various new thermoplastics and composite materials for the interiors. Each was originally delivered with polyurethane cushions; currently operators and manufacturers are involved in covering these cushions with fire blocking materials to upgrade fire safety.

The two piston powered aircraft use gasoline fired heaters without fire detection or fire suppression capability to provide cabin heat and ram air flow to provide outside air for cabin and cockpit cooling. The remainder of the aircraft are turbine powered, turboprop aircraft that use engine bleed air for heating and cooling of the interior air. The Beech 99, Cessna 402, deHavilland Twin Otter, Embraer Bandeirante, Piper Navajo and Shorts 330 are unpressurized aircraft while the BAe Jetstream 3100, Beech 1900, Embraer Brasilia and Fairchild Metro III are of pressurized design. The four pressurized aircraft are of newer design. The unpressurized aircraft have oxygen available for the pilots and passengers, often in portable storage form. The pressurized aircraft feature cabin oxygen for the passengers. Each of these aircraft reflects their operating environment of short, low altitude flight legs, not requiring design of oxygen systems characteristic of large commercial aircraft. In some of the aircraft, the fixed oxygen system is an option picked only by operators faced with the need for sustained high altitude operations, such as in mountainous areas. In these aircraft, oxygen is meant for emergency use of the crew and individual passengers with a temporary need.

The overall trend in the design of commuter airliners, as seen in this sample, is that of increasing sophistication in application of materials, in the newer aircraft, similar to that found in large commercial aircraft. With the exception of the deHavilland Twin Otter and the Shorts 330, these aircraft are small and offer relatively high performance.

APPENDIX

STANDARD DISTRIBUTION

Civil Aviation Authority (5)
Aviation House
129 Kingsway
London WC2B 6NN England

DOT-FAA AEU-500 (4)
American Embassy
APO New York, NY 09667

Embassy of Australia (1)
Civil Air Attache
1601 Mass. Ave. NW
Washington, DC 20036

University of California (1)
Service Dept Institute of
Transportation Standard Lib
412 McLaughlin Hall
Berkely, CA 94720

Scientific & Tech. Info FAC (1)
ATTN: NASA Rep.
P.O. Box 8757 BWI Airport
Baltimore, MD 21240

British Embassy (1)
Civil Air Atache ATS
3100 Mass. Ave. NW
Washington, DC 20008

Northwestern University (1)
Trisnet Repository
Transportation Center Library
Evanston, ILL 60201

Director DuCentre Exp DE LA (1)
Navigation Aerineene
941 Orly, France

ANE-40	(2)	ACT-61A	(2)	ASW-53B	(2)
ASO-52C4	(2)	AAL-400	(2)	AAC-64D	(2)
APM-13 Nigro	(2)	M-493.2 Bldg.10A	(5)	ACE-66	(2)
AEA-61	(3)			ADL-1	(1)
ADL-32 North	(1)	APM-1	(1)	ALG-300	(1)
AES-3	(1)	APA-300	(1)	ACT-5	(1)
ANM-60	(2)	AGL-60	(2)	AWS-100	(1)

ACT-300 Distribution

DOT/FAA National Headquarters
APA-300
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA Great Lakes Region (2)
AGL-60
O'Hare Office Center
2300 East Devon Avenue
Des Plaines, IL 60018

DOT/FAA Southwest Region (2)
ASW-53B
P.O. Box 1689
Fort Worth, TX 76101

DOT/FAA Mike Monroney Aeronautical
Center (2)
AAC-64D
P.O. Box 25082
Oklahoma City, OK 73125

DOT/FAA Central Region (2)
ACE-66
601 East 12th Street
Federal Building
Kansas City, MO 64106

DOT/FAA National Headquarters
ADL-1
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ALG-300
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA Technical Center
Public Affairs Staff, ACT-5
Atlantic City Int'l
Airport, NJ 08405

DOT/FAA National Headquarters
ASF-1
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ASF-100
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ASF-200
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ASF-300
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
AST-1
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ADL-2A
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
AVS-1
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
AFS-1
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
ASF-200
800 Independence Avenue, SW.
Washington, DC 20591

DOT/FAA National Headquarters
AWS-1
800 Independence Avenue, SW.
Washington, DC 20591

ACT-300 Distribution

FAA, Chief, Civil Aviation (1)
Assistance Group, Madrid Spain
c/o American Embassy
APO-New York 09285-0001

Dick Tobiason (1)
ATA of America
1709 New York Avenue, NW.
Washington, DC 20006

FAA Anchorage ACO
701 C Street, Box 14
Anchorage, Alaska 99513

FAA Atlanta ACO
1075 Inner Loop Road
College park, Georgia 30337

FAA Boston ACO
12 New England Executive Park
Burlington, Mass. 01803

FAA Brussels ACO
% American Embassy, APO,
New York, NY 09667

FAA Chicago ACO
2300 E. Devon, Room 232
Des Plains, Illinois 6008

FAA Denver
10455 East 25th Ave., Suite 307
Aurora, Colorado 98168

Frank Taylor
3542 Church Road
Ellicott City, MD 21403

Mr. Gale Braden (FAA)
5928 Queenston St.
Springfield, VA 22152

Richard E. Livingston, Jr.
Director, Aerotech Operations for
the IAPA Group
1805 Crystal Drive, Suite 1112 South
Arlington, VA 22202

Al Astorga (1)
Federal Aviation Administration
(CAAG)
American Embassy, Box 38
APO-New York 09285-0001

Burton Chesterfield, DMA-603 (1)
DOT Transportation Safety Inst.
6500 South McArthur Blvd.
Oklahoma City, OK 73125

FAA Forth Worth ACO
P.O. Box 1689
Fort Worth, TX 76101

FAA Long Beach ACO
4344 Donald Douglas Drive
Long Beach, CA 90808

FAA Los Angeles ACO
P.O. Box 92007, Worldway Postal Center
Hawthorne, CA 90009

FAA New York ACO
181 So. Frankline Ave., Room 202
Valley Stream, NY 11581

FAA Seattle ACO
17900 Pacific Highway South, C-68966
Seattle, Washington, 98168

FAA Wichita ACO
Mid Continent Airport, Room 100 FAA Bldg.
1891 Airport Road
Wichita, KA 67209

Dr. Hans A. Krakauer
Deputy Chairman, International Airline
Pilots Association Group
Apartado 97
8200 Albufeira, Portugal

Geoffrey Lipman
Executive Director, President du Conseil
International Foundation of Airline
Passenger Associations
Case Postale 462, 1215 Geneve
15 Aeroport, Suisse, Geneva

Mr. Fred Jenkins, ANM-130L
Federal Aviation Administration
4344 Donald Douglas Drive
Long Beach, California 90808

Mr. Dan Gross
B-66 Technology Building
National Bureau of Standards
Washington, DC 20234

Dr. James M. Peterson
The Boeing Company
MS/73-43
Seattle, Washington 98124

Dr. John O. Punderson
E.I. Dupont De Nemours
P.O. Box 1217
Parkersburg, West VA 26102

Commander
U.S. Army AVSCOM
Attn: DRSAB-EI (Mr. John P. Dow)
4300 Goodfellow Blvd.
St. Louis, MO 63120

Mr. L. C. Virr
Civil Aviation Authority
Barbazon House
Redhill
Surrey RH1 1SQ
England

Mr. Ray Young
Engineering and Air Safety Dep't
Airline Pilots Association
1625 Massachusetts Ave., NW
Washington, DC 20036

Dr. Calyton E. Hathaway
Monsanto Company
800 N. Lindberg Blvd. Mail Zone R3B
St. Louis, MO 63166

Dr. Leo P. Parts
Monsanto Research Corp.
1515 Nicholas Road
Datyton, Ohio 45407

Mr. Matthew M. McCormick
National Transportation Safety Board
Bureau of Technoloty
Washington, DC 20594

Mr. A. Delman
The Wool Bureau, Inc.
Technical Services Center
225 Crossways Park Drive
Woodbury, L.I., New York 11797

Dr. L. Benisek
International Wool Secretariat
Technical Center, Valley Drive
Ilkley, West Yorkshire, LS29 8PB
England

Mr. John A. Leland
Username:
Dept E-29
Douglas Aircraft Co. 35-14
3855 Lakewood Blvd.
Long Beach CA 90846

Mr. Stan Ames
Fire Research Station
Borehamwood
Hertfordshire WDG 2BL
England

Mr. Arthur G. Thorning
Civil Aviation Authority
CAA House
45-59 Kingsway
London WC2B GTE
England

Mr. Lee Hoyt
Weber Aircraft Co.
2820 Ontario Street
Burbank, CA 91505

Julia M. Baer
Celanese Fibers Marketing Comp.
P.O. Box 32414
Charlotte, NC 28232

Mr. James O. Price
Heath Tecna Corp.
19819 84th Avenue South
Kent, Washington 98031

Mr. Richard M. Harrison
Custom Products Company
P.O. Box 699
Sun Valley, California 91352

Mt. T. E. Waterman
IIT Research Institute
10 West 35th Street
Chicago, Illinois 60616

Mr. Henri Branting
FAA Headquarters
AWS-120
800 Independence Avenue SW
Washington, DC 20591

Dr. James E. Mielke
Science Policy Research Div.
Congressional Research Services
Library of Congress
Washington, DC 20540

Mr. Thomas Madgwick
British Aerospace p.l.c.
Aircraft Group
Weybridge-Bristol Division
Filton House
Bristol BS99 7AR England

Mr. Joseph L. Buckley
Factory Mutual System
1151 Boston-Providence Turnpike
Norwood, Mass. 02062

Mr. John Hoffmann
Port of New York & New Jersey
Authority
One Path Plaza (4th Floor)
Jersey City, NJ 07306

Mr. Robert E. Kraus
Raychem Corp.
300 Constitution Drive
Menlo Park, California 94025

Mr. John A. Blair
Manager, Standards
E.I. DuPont de Nemours & Co. ;PP+R
Chestnut Run
Wilmington, Delaware 19898

Mr. Bill Martinez, Mgr. Data Service
AMI Industries, Inc.
P.O. Box 370
Colorado Springs, California 80901

Mr. J. J. Brenneman
Fire Protection Engineer
United Airlines, Inc.
P.O. Box 66100
Chicago, Illinois 60666

Mr. Edward L. Lopez
Lockheed Aircraft Corp.
Dept. 74-75, Bldg. 229-A
Box 551
Burbank, CA 91503

Dr. D. Kourtidis
Chemical Research Center
NASA/AMES Research Center
Moffett Field, CA 94035

Mr. C. Hayden Leroy
TE-10 Bldg. 10-A
National Transportation Safety Board
Washington, DC 20594

Mr. Richard Nelson
ANM-110
17900 Pacific Highway South
C-G8966
Seattle, WA 98168

Dr. Charles R. Crane
FAA, CAMI, AAC-114
P.O. Box 25082
Oklahoma, OK 73125

Mr. Reginald Utting
The Boeing Company
Commercial Airplane Group, 747 Div.
P.O. Box 3707
Seattle, Washington 98124

Dr. Joseph C. Reed
E.I. DuPont de Nemours & Co.
Plastics Department
Fluorocarbons Division
Wilmington, Delaware 19898

Dr. Fumiharu Saito
Building Research Institute
Ministry of Construction
Tatehara-1 Oho-Machi
Tsukuba-Gun
Ibaraki Prefecture, Japan

Dr. Robert Keith
Laboratory Industrial Medicine
Eastman Chemical Company
Kingsport, Tenn. 37662

Mr. Kenton D. Warner
Puritan-Bennet Aero Systems Co.
10800 Pflumm Road
Lenexa, Kansas 66215

Mr. Geroqe Veryioglou
Systems Technology Staff
Boeing Commercial Airplane Co.
P.O. Box 3707, MS 77-70
Seattle, WA 98124

Mr. Donald Schroeder
Federal Aviation Administration
APM-710
800 Independence Ave. SW
Washington, DC 20591

Mr. Calvin J. Cruz
Textile Fibers Dept.
E.I. DuPont deNemours & Co., Inc.
Wilmington, Delaware 19898

Dr. C. Perry Bankston
Energy and Materials Research Sec.
Jet Propulsion Laboratory
4800 Oak Grove Drive
Pasadena, California 91103

Mr. Joseph A. Krist
Athol Manufacturing Corporation
1350 Broadway
New York, New York 10018

Mr. W. G. Dye
Director of Engineering
Fairchild Burns Company
1455 Fairchild Drive
Winston Salem, NC 27023

Mr. Peter Meiklem
Civil Air Attach's (Safety)
British Embassy
3100 Massachusetts Ave. NW
Washington, DC 20008

Dr. H. R. Dvorak
Wesson and Associates, Inc.
510 South Webster
Postal Box 1082
Norman, OK 73070

Mr. Erich Feldkirchner
Airbus Industrie
Headquarters, BP No. 33
31700 Blagnac, France

Ms. Diane Boulavsky
American Textile Mfgs. Institute
1101 Connecticut Ave. NW
Suite 350
Washington, DC 20036

Mr. Gregory Smith
B.F. Goodrich Technical Center
P.O. Box 122
Avon Lake, Ohio 44012

Mr. George M. Johnson
Chief Chemist
Pan American Airways, Inc.
Bldg. 208 Room 2228
J F Kennedy Int'l Airport
Jamaica, New York 11430

Dr. Lloyd H. Back
Energy and Materials Research Sec.
Jet Propulsion Laboratory
4800 Oak Grove Drive
Pasadena, California 91103

Dr. A. Carlos Fernandez-Pello
Mechanical Engineering Department
University of California, Berkely
Berkely, California 9420

Mr. S. F. Taylor
College of Aeronautics
Cranfield Institute of Technology
Cranfield, Bedford MK30AL England

Mr. William R. Kane
System Engineering Group
ASD/ENFEF
Wright-Patterson AFB, Ohio 45433

Mr. A. J. Christopher
Royal Aircraft Establishment
Materials Department
South Farnborough
Hants, England

Manager
Flight Attendant Training & Standard
Western Airlines
6060 Avion Drive
Los Angeles, California 90009

Mr. Everett A. Tustin
Boeing Commercial Airplane Company
P.O. Box 3707, M/S GF-26
Seattle, Washington 98124

Mr. R. G. Clodfelter
AFWAL/POSH
Wright-Patterson AFB
Ohio 45433

Dr. Edwin Smith
Ohio State University
140 W. 19th Avenue
Columbus, Ohio 43214

Mr. Walter Perkowski
The Boeing Company
Commercial Airplane Group
P.O. Box 3707, MS/73-43
Seattle, Washington 98124

Mr. William Snoddy
American Airlines
P.O. Box 51009 Mail Stop #10
Tulsa, Oklahoma 74151

Mrs. Charlotte Gebhart
Rohm & Haas Company
Independence Mall West
Philadelphia, PA 19105

Wm. Kirkham, Phd., Md, AAC-144
DOT/FAA/ CAMI
Aeronautical Center
P.O. Box 25082
Oklahoma City, Oklahoma 73125

Mr. Henry J. Roux
Product Fire Performance
Armstrong World Industries, Inc.
Lancaster, PA 17604

Mr. John Ed Ryan
National Forest Products Assoc.
50 North Franklin Turnpike
P.O. Box 314
Hohokus, New Jersey 07423

C. M. Sliepcevich
Flame Dynamics Laboratory
University of Oklahoma
1215 Westheimer Street
Norman, Oklahoma 73069

Mr. Louis Frisco
Wire & Cable Division
Raychem Corp.
300 Constitution Drive
Menlo Park, California 94205

Dr. John A. Parker
Chemical Research Projects Office
NASA/AMES Research Center M.S. 223-6
Moffett Field, California, 94035

Bernard Grendahl, Mgr. Tech. Service
Aerospace Division
Universal Oil Products Company
Bantam, Conn. 06750

A. Tewarson
FMRC
1151 Boston-Providence T'Pke
Norwood, Mass. 02062

Dr. Rosalind C. Anderson
Arthur D. Little, Inc.
Acorn Park
Cambridge, Mass. 02140

Mr. Matthew Finucane
Aviation Consumer Action Project
P.O. Box 19029
Washington, DC 20036

Mr. Leo Fisher
Crest Foam
100 Carol Place
Moonachie, NJ 07074

Mr. Philip J. DiNenno
Professional Loss Control, Inc.
P.O. Box 446
Oak Ridge, TN 37830

Mr. James A. Milke
Department of Fire Protection
Engineering
University of Maryland
College Park, MD 20742

Mr. John P. Reese
Aerospace Industries Association
of America, Inc.
1725 Desales Street, N.W.
Washington, DC 20036

Mr. Jim Brown
General Dynamics Electric Boat Div.
Station CG2
Eastern Point Road
Groton, Conn. 06340

Mr. John R. Powers
Delta Airlines, Inc.
Hartsfield Atlanta
International Airport
Atlanta, Georgia 30320

Mr. S. M. Hooper
Eastern Airlines
Miami International Airport
Miami, Florida 33148

Dr. Charles P. Lazzara
US Bureau of Mines
Pgh. Research Center
P.O. Box 18070
Pittsburgh, PA 15236

Dr. James G. Quintiere
National Bureau of Standards
Bldg. 224, Room B-356
Washington, DC 20234

Mr. Stan Martin & Assoc.
860 Vista Drive
Redwood City, California 94062

Mr. A. L. Bridgman
General Electric Company
Plastics Technology Department
1 Plastics Avenue
Pittsfield, MA 01201

Mr. Walter T. Clark Jr.
Clark Engineering Service
312 E. Main Street
Lancaster, Texas 75146

Commanding General
U.S. Army Test & Evaluation
Command
Attn: DRSTE-AD-A (D. Conley)
Aberdeen Proving Ground, MD 21005

Mr. Charles Macaluss
U.S. Testing
5555 Telegraph Road
Los Angeles, CA 90040

Mr. Steve Waldrip
Republic Airlines
7500 Airline Drive
Minneapolis, Minnesota 55450

T. F. Laughlin, Jr.
Lockheed-California Company
D/98-01, B/90-4, A-1
P.O. Box 551
Burbank, California 91520

Kirke Comstock
Manager of Interior Engineering
United Airlines Maint. Oper. Center
Engineering Department
San Francisco International Airport
San Francisco, California 94128

Dr. John Levertton
Civil Regulations Manager
Civil Business Group
Westland Helicopters, LTD.
Yeovil, BA20 2YB
Somerset, England

Dr. Dale G. Onderak
John Schneller & Associates
6019 Powdermill Road
Kent, Ohio 44240

Mr. Mike Bauccio
U.S. Army Aviation R&D Command
AVSCOM/DRSAV-NS
St. Louis Missouri 63120

Mr. Vyto Babrauskas
National Bureau of Standards
Bldg. 224, Room A-345
Washington, DC 20234

Mr. Pascal Dranitsaris
Ontario Research Foundation
Sheridan Park Research Community
Mississauga, Ontario, Canada
L5K1B3

Mr. V. W. Ballenger
Director, Engineering and Maint.
Air Transport Association
1709 New York Avenue, N.W.
Washington, DC 20006

Mr. William K. Greer
General Electric Company
1 Plastics Avenue
Pittsfield, Massachusetts 01201

D. A. Radice
Manager, Flexible Sales
CPR Division of Upjohn Company
555 Alaska Avenue
Torrence, California 90503

Mr. Micheal Tyler
Aviation Safety Bureau
Transport Canada
Ottawa, Ontario, Canada KIA0N8

Mr. Charles W. McGuire
Department of Transportation
400 7th Street S.W.
Washington, DC 20590

Mr. A. T. Peacock
Douglas Aircraft Company
Internal Mail Code 36-41
3855 Lakewood Blvd.
Long Beach, California 90846

Mr. Eric W. Simmons
Ontario Research Foundation
Sheridan Park Research Community
Mississauga, Ontario, Canada
L5K1B3

Mr. James H. Keeler
General Electric Company
1 Plastics Avenue
Pittsfield, Massachusetts 01201